

CITY OF ALBUQUERQUE



April 17, 2015

Diane Hoelzer, P.E.
Mark Goodwin and Associates
P.O. Box 90606
Albuquerque, NM 87199

Re: Sawmill Crossing Unit 2, Grading Certification-Final
Engineer's Stamp dated: 12-5-14, (H13D057)
Certification dated: 4-9-15

Dear Ms. Hoelzer,

After a site visit and based upon the information provided in the Certification received 4-9-15, the above referenced certification is not acceptable to allow final building inspections/Certificates of Occupancy on lots in Unit 2. The curb and gutter has not been installed, nor the streets and there are no pads for lots 61-63,

If you have any questions, you can contact me at 924-3986.

PO Box 1293

Albuquerque

New Mexico 87103

www.cabq.gov

Sincerely,

Rita T. Harmon, P.E.
Senior Engineer, Hydrology
Development and Building Services

C: e-mail