



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Avanyu Plaza - 2500 12th Street NW				
Location:	12th Street & Menaul				
Site Contact Name & Agency	Mark Thompson	ESC File No.	H13E111		
		NPDES Id. No.	NMR10I02Z		
Inspection Date:	06/03/19	Start/End Time:	0945/100hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	STABILIZED				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	69*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/03/19