



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name and Location	Mounday Amen 2nd & Prospect		
Site Contact Name & Agency	Pat Joseph PJ Development	ESC File No.	H14E067
Date of Inspection	2-12-18	Start/End Time	10:05 / 10:10
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	Stabilized		

Type of Inspection:

☒ Regular • During storm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up

Weather Information

Weather at time of this inspection?

Temperature: ~ 40 F°

☒ Clear • Cloudy • Rain • Sleet • Fog • Snowing • Windy

Has there been a storm event since the site was Permitted? • Yes • No

Amount: • < 1/4" • 1/4" to 3/4" • > 3/4" • Snow _____

Erosion & Sediment Control Inspection

Entrance / Track-Out N/A

Sediment Controls / Silt Fence,
Inlet Protection, Wattles, etc.

Stabilized

Inspection Reports

Erosion Controls
Housekeeping/Pollutant Controls

gravel, pond

Debris/Pollutants/Sediment in MS4
Notes

Is site being maintained in compliance with the Drainage Ordinance? • Yes • No

Signature

Date

Curtis Cherne 2-12-18