

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	H14E	110 Project Name:			U-Haul Albuquerque Westside			
NPDES Id. No. NMR10		03MS Location:			2217 4th Street			
8/1	1/2021	Owner		•	Contractor			
Operator		Amerco Real Estate Company						
Contact name & title		Tom Neill						
e-mail		tom_neill@uhaul.com						
Contact Phone #		505-259-0339						
COA Inspector		Thomas Evans			Start/End Time: 12:45 PM-12:50 PM			
Construction Phase:					uction, BMP's			
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weather at time of i				ear	Tempera	ature: ~	84	
Estimated	l date of last s	torm 0.25" o	r greater		5/31/2021			
Item	Deficiency/ Corrective Action							
Number								
1	No posting of NOI permit coverage. Post signage of NOI permit coverage in a location clearly visible to the public.							
2	Self-inspection report not provided upon last request.							
2	isen-inspection report flot provided apoil last request.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	None o	n file	
Natas	Cil+ fonce and	d mulah saaks	hava baan in	stalled Ne se	tivity on site			
Notes:	Silt rence and	i muich socks	, nave been in	stalled. No ac	tivity on site.			
	· 	· 	· 			·	-	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov