

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	H14E	112 Project Name:			Broadway/McKnight Apartments		
NPDES Id. No.	NMR1003ZY L		ocation:		300 McKnight Ave NE		
4/26/2023		Owner			Contractor		
Operator		Albuquerque Housing Authority			Pavilion		
Contact name & title		Daniel Foster			Todd Lay		
e-mail		dfoster@abgha.org			tlay@pavillionconstruction.com		
Contact Phone #		505-764-3925			350-0921		
COA Inspector		Doug Hughes			Start/End Time: 1:30 PM		
	tion Phase:				CO		
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up
Weath	er at time of i	nspection? Clear			Temperature: ~ 65		
Estimated date of last storm 0.25" or greater 3/16/2023							
Item							
	Deficiency/ Corrective Action						
Number							
1	The City has determined that the ground cover on Tract 1 satisfies the Final Stabilization Criteria						
	CGP2.2.14.c, so you must remove the BMPs and send documentation of the Final Stabilization to the						
	EPA with a Notice of Termination (NOT) per CGP 8.2 to end your coverage under the CGP. This step is						
	independent of the Building Permit and Certificate of Occupancy. Please copy me with the						
	documentation and the EPA's acceptance of the NOT.						
2							
3							
4							
•							
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspection Reports		required	Latest re	oort Date:	n/a	
Notes:							
CGP coverage is active.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov