



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	H15E068	Project Name:	Maverik		
NPDES Id. No.	NMIR1002QF	Location:	1901 Menaul blvd NE		
6/21/2021	Property Owner		Contractor		
Operator	Maverik, Inc.		Maverik		
Contact name & title	Troy Jergensen		Kelly Irons		
e-mail	troy.jorgensen@maverik.com		kelly.iron@maverik.com		
Contact Phone #	801-335-3851		801-419-2298		
COA Inspector	Doug Hughes		Start/End Time:	1:00 PM-1:10 PM	
Construction Phase:	Stabilization				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	Clear		Temperature: ~	88	
Estimated date of last storm 0.25" or greater					
Item Number	Deficiency/ Corrective Action				
1	None observed.				
2					
3					
4					
5					
6					
7					
2.1	Discharge off site? (Y/N)	Yes			
4	Self Inspection Reports		Latest report Date:	2/15/2021	

Notes:	Rock and crusher fines for stabilization.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420
jhughes@cabq.gov

Thomas Evans 06/22/2021