

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. H16E				American Furniture Demo\			
NPDES Id. No. NMR10				3535 Menaul Blvd NE			
8/8/2024		Owner		Contractor			
Operator		Vista Oriente, Ltd. Co.			Guzman Construction Solutions, LLC		
Contact name & title		Jeff Jesionowski			Eddie Gonzales		
e-mail		jeff@amcdevelopment.net			eddie@guzmancs.com		
Contact Phone #		505-259-0991			505-975-8149		
COA Insp		Chancellor English			Start/End Time: 2pm		
Construction Phase:					f building		1
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
Weather at time of i					Temperature: ~ 97		
Estimated date of last storm 0.25" or greater 6/30						6/30/2024	
Item							
Number	Deficiency/ Corrective Action						
1	The SWPPP and self-inspection reports were unavailable at the time of inspection in violation of CGP						
	Parts 4.7.3 and 7.3. Required mitigation: You must keep a copy of your up-to-date SWPPP and self-						
	inspection reports at the site or at an easily accessible location so that it can be made available at the						
	time of an on-site inspection per CGP Parts 4.7.3 and 7.3.						
	time of an on-site inspection per Cor Parts 4.7.3 and 7.3.						
				_			
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	ion Reports	s no	Latest rep	oort Date:	N/A	
			-		-		
Notos							
Notes:							
Superintendent was on site, but did not have the SWPPP							

City of Albuquerque Stormwater Inspector Signature and date: 8/15/2024

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English