

	General Information	
Project Name and Location	RICHMOND SWITCHING STATI	191
Site Contact Name & Agency	5haron Brown ESC File No. H16E08 1-23-18 Start/End 7:30/2:46	
Date of Inspection	1-23-18 Start/End 7:30/2:46	
Inspector Name, COA Dept.	Stanice "Totten" Elliott, Stormwater Quality	
Describe Present Phase of Construction	STABILIZED	
Type of Inspection: Regular During stor	orm event Post-storm event (> 0.5 inch) 311 / Complaint Response Follow-U	Jр
	Weather Information	
Weather at time of this inspecti	tion? Temperature: ~ 45 Rain Sleet Fog Snowing Windy	_ F°
Has there been a storm event si	since the site was Permitted? Tyes \(\square\) No	
Amount: $\Box < \frac{1}{4}$ " to $\frac{3}{4}$ " to $\frac{3}{4}$	³ / ₄ " □ > ³ / ₄ " □ Snow"	
	Erosion & Sediment Control Inspection	
Entrance / Track-Out Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc. Erosion Controls Housekeeping/Pollutant Control	gravel a	
Debris/Pollutants/Sediment in Notes Is site being maintained in compliance	mce with the Drainage Ordinance Ayes No A. Cluot 1-23	
,	Signature Date	-

From:

Brown, Sharon <Sharon.Brown@pnmresources.com>

Sent:

Wednesday, January 24, 2018 4:17 PM

To:

Cherne, Curtis

Subject:

RE: [External] RE: Richmond Substation

Perfect. Thank you so much for your time and patience. I am so glad to have this one done myself!

Sharon Brown
PNM Environmental Services
505-241-2058 office
505-263-4845 cell





From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Wednesday, January 24, 2018 4:12 PM

To: Brown, Sharon

Subject: [External] RE: Richmond Substation

CAUTION: This email was received from an **EXTERNAL** source, use caution when clicking links or opening attachments. If you believe this to be a malicious and/or phishing email, please send this email as an attachment to

pamControl@pnmresources.com

Sharon,

Good afternoon.

I've been popping in from time to time to check on progress.

An inspector was out there yesterday and determined the site to be stabilized.

The inspection form is attached, which is the City "signing-off" on the site.

I'll drive by another day and check it out, I'm sure it looks nice.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

From: Brown, Sharon [mailto:Sharon.Brown@pnmresources.com]

Sent: Wednesday, January 24, 2018 4:03 PM



2 (2-20mm) 2 (2-20mm)					
	General I	nformation			
Project Name	Richmond	Surtemi	s Statio	×	
and Location	Richman	LM	enaul		
Site Contact Name & Agency			ESC File No.		
Date of Inspection	12-13-17		Start/End 7	145/	
Inspector Name, COA Dept.			ormwater Qualit		
Describe Present Phase of Construction	Describe Present				
Type of Inspection: Regular • During stor	m event • Post-storm even	1		• •	
	Weather I	nformation		,	
Weather at time of this inspecti			Te	emperature: ~ 35 F°	
_	Rain · Sleet · Fog ·	Snowing •		•	
Has there been a storm event si					
Amount: • < 1/4" • 1/1" to 3	4" > 3/4"	• Snow"			
	Erosion & Sedimen	nt Control Inspec	tion		
Entrance / Track-Out	VIA				
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	DAKNO				
Erosion Controls Housekeeping/Pollutant Contro	ols				
Debris/Pollutants/Sediment in Notes		Scapin			
Is site being maintained in complian	ce with the Drainage Ordinance ?	Ye) No	Cont G (- la 12-13-17 Date	
1		20,	-		

ECS File: #1656831)



	General Information			
Project Name and Location	Richmad Swifthing Station Richmond & Menaul Shown Brown Contact Phone #1 5eA			
Site Contact Name & Agency	Shan Brinn Contact Phone #/ Fed Su			
Date of Inspection	6-17-17 Start/End 8:56 /9:16			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	Interior complete			
Type of Inspection:	Destruction of the 211/Complete Barrage & Fallow He			
Regular · During stor				
Carr	Weather Information			
Weather at time of this inspect	ion? Temperature: ~_/F° Rain · Sleet · Fog · Snowing · Windy			
Has there been a storm event st Amount: < 1/4" (4" to 3				
	Erosion & Sediment Control Inspection			
■ Entrance / Track-Out	NA			
 Sediment Controls / Silt F Check Dams, Waddles 				
	, Seed, hu rand en exterior			
Housekeeping/Pollutant Controls Lots of frush east 5, L				
• Debris/Pollutants/Sediment in MS4				
Notes				
Is site being maintained in complian	nce with the Drainage Ordinance? Yes No Cut o chu 6-12-17 Signature Date			

Lush Landscap plan Cars-17
word Richmood Sunterly State

Business water comp on ADD

LIU have to charge Conssign plan

Spike w/ Lawie Mye

John w/ Caurie Myce

14 you have created quit a

firestorn over here

From:

Brown, Sharon <Sharon.Brown@pnmresources.com>

Sent:

Monday, June 19, 2017 9:27 AM

To:

Cherne, Curtis

Subject:

RE: [External] Richmond Switching Station inspection

Curtis- Thank you for the pics. I am following up on the proposed landscaping. My understanding is Laurie Moye is working on it for approvals, but it is planned to move forward.

I will be in contact when confirmed.

Thanks,

Sharon Brown
PNM Environmental Services
505-241-2058 office
505-263-4845 cell





From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Tuesday, June 13, 2017 3:07 PM

To: Brown, Sharon

Subject: [External] Richmond Switching Station inspection

WARNING: EXTERNAL SENDER. NEVER click links or open attachments without positive sender verification of purpose. DO NOT provide your user ID or password on sites or forms linked from this email.

Sharon,

On March 17th I asked you if you would have the rock around the outside of the switching station in before monsoon season. I went out there today expecting to see it. Not there.

You do have some weed growth that will help with erosion, but that may not be intended.

You do have some trash and a homeless camp on the east side of the site.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

This message has been analyzed by Deep Discovery Email Inspector.

From:

Cherne, Curtis

Sent:

Tuesday, June 13, 2017 3:07 PM

To: Subject: 'Sharon.brown@pnmresources.com' Richmond Switching Station inspection

Attachments:

trash.jpg; trash2.jpg; no_rock.jpg; homeless_Camp.jpg

Sharon,

On March 17th I asked you if you would have the rock around the outside of the switching station in before monsoon season. I went out there today expecting to see it. Not there.

You do have some weed growth that will help with erosion, but that may not be intended.

You do have some trash and a homeless camp on the east side of the site.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: 416 150837



	General Info	rmation			
			_/ / ·		
Project Name and Location	Richard Swidehing station Richard & Menaul				
and Location	Richard 4	Lenaul			
	Sherm Brown		ontact Pho	1	
Site Contact Name & Agency	Prn		-mail		241-2058
Date of Inspection		S	Start/End	910	241-2058 90/9650
	3-17-17	tis Cherne, Storn	Time Our		10/ 1/30
Inspector Name, COA Dept.			nwater Qua	anty	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.g		Stormwater	One	
Inspector Qualifications Describe Present	Qualified Compliance Inspector			One	
Phase of Construction	placing grand	125, 61 L	walls		
Type of Inspection:	¥ ·				
Regular • During stor	rm event • Post-storm event (>	0.5 inch) • 311	/ Complaint	Respo	onse • Follow-Up
	Weather Info	ormation			
Weather at time of this inspect				Temp	erature: ~ SI F°
1	Rain · Sleet · Fog · Sne	L	ndy ————		
Has there been a storm event s Amount: < 1/4" 103	since the site was Permitted? • 34" • > 34" •	Snow"			
	Erosion & Sediment (Control Inspection	n		
Entrance / Track-Out	ok				
 Sediment Controls / Silt I Check Dams, Waddles 	α				
Erosion Controls / Mulch	, Seed, flaux 5	ravel in	s.te -		on outsit
Housekeeping/Pollutant C	Controls <u>olc</u>				· · · · · · · · · · · · · · · · · · ·
Debris/Pollutants/Sedime	ent in MS4				
Notes					
Is site being maintained in complian	nce with the Drainage Ordinance?	Yes No Signo	ature	ch	3-17-17 Date

From: Brown, Sharon <Sharon.Brown@pnmresources.com>

Sent: Friday, March 17, 2017 1:52 PM

To: Cherne, Curtis

Subject: RE: [External] Richmond switching station

Hi Curtis- Yes, we are almost finished with the inside. Once completed and we can string the wires, we will complete the landscaping on the outside. There is no point now if the trucks will drive all over it. Our in service date is May 1... I will push to have landscape complete ASAP afterwards.

Thanks!

Sharon Brown
PNM Environmental Services
505-241-2058 office
505-263-4845 cell





From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Friday, March 17, 2017 1:49 PM

To: Brown, Sharon

Subject: [External] Richmond switching station

This is an EXTERNAL email. DO NOT click links without positive sender verification of purpose. Never enter USERNAME or PASSWORD on linked pages from this email.

Sharon,

Good afternoon.

It had been awhile since I was out at the switching station. The contractor was placing gravel inside the walls. I asked him if he was doing the outside and he said he wasn't.

Do you know if you'll have gravel outside the walls before monsoon season (typically July 1)?

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

ECS File: 416 E 0 830



	General Informati	on		
Project Name and Location	Richmond Switcher Richmond and	sfattin		
Site Contact Name & Agency	Shoron Brown	Contact Phon	241-2058	
Date of Inspection	6-1-16	Start/End Time		
Inspector Name, COA Dept.	Curtis Ch	erne, Stormwater Qual	ity	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of St	tormwater- Stormwater (One	
Describe Present Phase of Construction	erecting large poles	•		
Type of Inspection: Post-storm event (> 0.5 inch) · 311 / Complaint Response · Follow-Up				
	Weather Informati	ion		
Weather at time of this inspect	ion? Rain · Sleet · Fog · Snowing		Γemperature: ~ <u>ੳ 0</u> F°	
Has there been a storm event's Amount: • < 1/4" to	ince the site was Permitted? Yes 4" > 34" Snow			
	Erosion & Sediment Contro	ol Inspection		
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles Erosion Controls / Mulch Housekeeping/Pollutant C 	, Seed,	Drive par 6		
■ Debris/Pollutants/Sediment in MS4				
Deuris/1 ondians/Sediment in 19154				
• Notes		<u> </u>		
Is site being maintained in complian	nce with the Drainage Ordinance ? Yes	Signature	Ane C-1-14 Date	

ECS File: #16 70 830



	General Information
Project Name and Location	Richmas strifething Staffin Richmas & Menaul 5 harm Brown Contrat Phone # 241 2050
Site Contact Name & Agency	OM
Date of Inspection	4-19-16 Start/End Time 12:00/ 12:00
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Phase of Construction Type of Inspection:	51 to grasis, walls but, pok fon's in, NO grasul/
Regular • During stor	orm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up
	Weather Information
	Rain · Sleet · Fog · Snowing · Windy since the site was Permitted? · Yes · No
	Erosion & Sediment Control Inspection
 Entrance / Track-Out Sediment Controls / Silt I Check Dams, Waddles Erosion Controls / Mulch Housekeeping/Pollutant College Debris/Pollutants/Sedime Notes Culls 	controls She crown to draw Whrand And Should have gravel
Is site being maintained in complia	ance with the Drainage Ordinance? Yes No Gut a fun 4-11-16 Signature Date

ECS File: 416 E0 8319



	General Information				
Project Name and Location	Richman Switching Steation Richmans and Menaul Sharan Brown PNM				
Site Contact Name & Agency	Shan Brown	Contact Phone #	241-2058		
Date of Inspection	11-10-15	Start/End //a	00 /1:20		
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater	er- Stormwater One			
Describe Present Phase of Construction	Fini graved, so Lewelly	Construct	hil		
Type of Inspection: Regular During stor	rm event • Post-storm event • 311 / Com	plaint Response •	Follow-Up		
	Weather Information				
Has there been a storm events	Rain · Sleet · Fog · Snowing · ince the site was Permitted? · · · · No 4" · > 34" · Snow" Erosion & Sediment Control Inspec	Windy	nperature: ~66F°		
	ne FAILED or REQUIRE MAINTENANCE				
 Sediment Controls / Silt I Check Dams, Waddles 	Fence, s, etc. New 5.11 force				
 Erosion Controls / Mulch 	, Seed,				
• Wind Blown Erosion	~6				
 Housekeeping / Pollutant 	Controls gook				
Is site being maintained in complia	ince with Const. Och. I clinit: / I cy 140	ut chu			

H16 E0830

From: Brown, Sharon <Sharon.Brown@pnmresources.com>

Sent: Wednesday, September 02, 2015 12:45 PM

To: Cherne, Curtis

Subject: RE: [External] Richmond Station SWPPP inspection

No problem... It has been up right next the entrance... maybe you just needed more coffee that morning. ©

FYI... I have received confirmation (and saw them out this morning) that Franklin's swept the street and gutter.

Thanks again.

Sharon Brown PNM Environmental Services 505-241-2058 office 505-263-4845 cell

From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Wednesday, September 02, 2015 12:22 PM

To: Brown, Sharon

Subject: RE: [External] Richmond Station SWPPP inspection

Sharon,

It is completely adequate. I just don't think it was there when I was there. If it was, my bad and apologies.

Curtis

From: Brown, Sharon [mailto:Sharon.Brown@pnmresources.com]

Sent: Wednesday, September 02, 2015 8:18 AM

To: Cherne, Curtis

Subject: RE: [External] Richmond Station SWPPP inspection

Hi Curtis- Is the attached picture not contain the adequate postings? Thank you for your assistance.

Sharon Brown PNM Environmental Services 505-241-2058 office 505-263-4845 cell

From: Cherne, Curtis [mailto:CCherne@cabq.gov]

Sent: Friday, August 28, 2015 3:11 PM

To: Brown, Sharon

Subject: [External] Richmond Station SWPPP inspection

Sharon,

Good afternoon.

I visited the Richmond Station this morning for a SWPPP inspection. The grading looks real nice and the site was very clean. However, there were a few issues.

1. There was a breach in the silt fence in the northwest corner. It wasn't bad at this point, but if we get some rain it will get worse as the large "bench" (see breach-basin.jpg) area along the northern edge of the project drains

ECS File: #/6 E 8930



The state of the s					
	General In	,			
Project Name and Location	Richmond and	y Station Merane	ESC PERMIT #		
Site Contact Name & Agency	Sharon Brown PNM		Contact Phone #	241-2058	
Date of Inspection	8-28-15 Start/End 10:SW 11:15				
Inspector Name, COA Dept.	Cu	ırtis Cherne, St	tormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.	gov			
Inspector Qualifications	Stormwater USA				
Describe Present Phase of Construction	Fin graded				
Type of Inspection: Regular Follow-Up	Random • During storm even	t • Post-stor	m event • 311/0	Complaint Response	
	Weather In	formation			
	Rain · Sleet · Fog · S			perature: ~_ ØS F° her:	
	since the site was Permitted?		. II	· Snow "	
Amount: • < 1/4 • 1/4 10	3/4" · > 3/4" Intensity:			3110W	
	Erosion & Sediment	Control Hisped	CHOIL		
 Check anv BMPs that h Entrance / Off Tracking Sediment Controls / Silt I 	entrace of Lriv Entrace of Lriv Ence,	ring arun	1 st frage	in guther un prohim	
Check Dams, Waddles Erosion Controls / Mulch	s, etc. Most OC, 9	track in	VW Co	T. N.C.	
Wind Blown Erosion	Z.~D				
Housekeeping / Pollutant	. Controls				
Is site being maintained in complia	ance with Const. Gen. Permit ? Ye.		into chen	0-29-1	
		Si	ignature	Date	

From:

Cherne, Curtis

Sent: To: Friday, August 28, 2015 3:11 PM 'sharon.brown@pnmresources.com'

Subject:

Richmond Station SWPPP inspection

Attachments:

breach-basin.jpg; driving-around-rock.jpg; sediment-gutter.jpg; silt-fence-breach-

downstream.jpg; silt-fence-breach-upstream.jpg; track-out.jpg

Sharon,

Good afternoon.

I visited the Richmond Station this morning for a SWPPP inspection. The grading looks real nice and the site was very clean. However, there were a few issues.

- 1. There was a breach in the silt fence in the northwest corner. It wasn't bad at this point, but if we get some rain it will get worse as the large "bench" (see breach-basin.jpg) area along the northern edge of the project drains to this corner. Some wattles spaced a distance apart or check dams would help slow the water down before it gets to this corner. I am available to spend more time with you or the contractor on this one if you wish.
- 2. All of the silt fence was built very well except this one spot.
- 3. There was some track-out at the construction entrance. Mostly because it appears it is being driven around rather than over. The rock entrance is in good shape.
- 4. There was no posting sign. Please see Paragraph 1.5 of the CGP or give me a call for what is to be posted.
- 5. There was quite a bit of sediment in the gutter on Richmond Dr. This should be swept.

Standard mitigation time is seven days.

If you or the contractor have any questions, please let me know.

Please say "Hi" to Laurie Moye from me if you see her.

Curtis Cherne, PE Stormwater Quality City of Albuquerque 924-3420