



## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

### Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

### General Information

#### Inspector's Qualifications

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ **Regular** ☐ During storm event  
☐ Post-storm event

### Weather Information

#### Last Storm Event Information

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☒ **Clear** ☐ Cloudy ☐ Rain  
☐ Sleet ☐ Snowing ☐ High Winds  
☐ Partly Cloudy

Have any discharges occurred since the last inspection?

- Yes  No

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

- Yes  No

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

- Yes  No

If yes, where is it located?

Monitoring nearby gauge, NOAA and Cocorhas.

Has the Rain Event Page been filled out?

- Yes  No

Are there SDS sheets on site?

- Yes  No



## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

If yes, where are they located?

N/A No weather events applicable. SDS sheets with site super.

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

☐

Date Construction Resumed

☐

Measures Taken to Stabilize the Site:

### Construction Phasing

**Verify what stage of construction the project is in, and record dates when activities started and were completed.**

Installed BMPs

Completed

Started:

☐

Completed:

02/21

Site Clearing and Grading

Started:

☐

Completed:

☐

Installing Utilities

Started:

☐

Completed:

☐

Building Structure

Started:

☐

Completed:

☐

Paving and Walks

Started:

☐



# INSPECTIONS PLUS

## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

Completed:

☐

Final Grading/Stabilize Site

Started:

☐

Completed:

☐

Other

Started:

☐

### Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Fabric fence/ security fence Weighted  
wattles, drop inlet and outfall protection.  
Curbs and paving in place. Rip rap/  
aggregate-north side

Are all of the above controls installed?

Yes

No

Do any of the above controls need maintenance?

Yes

No

If any of the controls have not been installed or require maintenance,  
please list the control and explain.

N/A

Are the BMPs shown on the map?

Yes

No

Were there any changes to the SWPPP?

Yes

No

Has the SWPPP been updated?

Yes

No

Were the changes to the SWPPP implemented within 7 days?

Yes

No

List any new BMPs needed:

N/A

Notes:



## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

### Oversight Issues

A list of corrective actions will be supplied with this inspection.

#### **1. Are all slopes and disturbed areas not actively being worked properly stabilized?**

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

#### **2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?**

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

#### **3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?**

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

#### **4. Are discharge points and receiving waters free of any sediment deposits?**

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

#### **5. Are storm drain inlets properly protected?**

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

#### **6. Is the construction exit preventing sediment from being tracked into the street?**

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?



## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

### 7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

Maintenance Required?

### 8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

Maintenance Required?

### 9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

Maintenance Required

### 10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

Maintenance Required?

### 11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

Maintenance Required?

### 12. Has the Site map been updated to reflect current conditions?

Implemented?

Maintenance Required?



## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

### 13. Is the NOI posted?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

### 14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes	No
-----	----

Have there been any reportable quantities releases of hazardous materials?

Yes	No
-----	----

Additional Notes

BMPs are in place and congruent to site activities.

## Certification & Signatures

### Certification Statement:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

### Electronic Signature

**X** *Jeff Hart*

Date

April 12, 2021 at 8:37:36 AM MDT

Title

Senior Inspector



# INSPECTIONS PLUS

## General Permit SWPPP Inspection

Site Name:	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	Inspector:	Jeff Hart
Permit #:		Inspection Frequency:	Bi-weekly -
Date of Visit:	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

## Weather History

Precipitation  
Recorded



No  
Precipitation

Missed or data  
unavailable

### March

26 th 0.01" 27 th 0 28 th 0 29 th 0 30 th 0 31 st 0

### April

1 st 0 2 nd 0 3 rd 0 4 th 0 5 th 0 6 th 0 7 th 0  
8 th 0 9 th 0 11 th

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



# INSPECTIONS PLUS

## General Permit SWPPP Inspection

<b>Site Name:</b>	<u>Econo Lodge Demolition</u> <u>2412 Carlisle Blvd NE, Albuquerque, NM 87110</u>	<b>Inspector:</b>	Jeff Hart
<b>Permit #:</b>		<b>Inspection Frequency:</b>	Bi-weekly -
<b>Date of Visit:</b>	Apr 9, 2021, 1:00:15 PM	Last Rain Event --	Last Precipitation Saturday, March 27, 2021, 0.01" 48h Forecast 15% Chance of Rain

There Are No Action Items