

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
ESC File No.	. H17E097		oject Name:	Carlisle Crossing					
NPDES Id. No.	NMR1005HJ N	NMR10040H Lo	cation:		2100 C	arlisle Blvd. NE			
3/30/2023 Owner					Contractor				
Operator		Carlisle Associates LP			Jaynes Corp.				
Contact name & title		Dave Rosen C/O Joe Bernabeo			stetson.chandler@jaynescorp.com				
e-mail		jbernabeo@rosenmgmt			stetson chandler				
Contact Phone #		505-304-4516			432-249-0659				
COA Inspector		Doug Hughes			Start/End Tim		•		
Construction Phase:					andscaping and building incomplete.				
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up		
Weather at time of inspectio					Temperature: ~ 45		45		
Estimated	date of last s	storm 0.25" or	greater			3/16/2023			
Item			- 6						
Number			Deficienc	cy/ Correctiv	e Action				
	TI NINADEC IE	211.0	•	5	111 212 41	24005111			
1	The NMDES ID# for the Owner is wrong on the Posting. It should be NMR1005HJ								
2	Please provide latest self-inspection report and all future reports.								
	General information comment - Loading docks next to east side of building, two Pad sites, and all								
	landscaping are still disturbed and need to be stabilized You must continue permit coverage, self-								
	inspections, SWPPP and BMP maintenance until the City determines that the Final Stabilization Criteria								
	CGP2.2.14.c has been satisfied. Then you must remove the BMPs and send documentation of the Final								
	·								
	Stabilization to the EPA with a Notice of Termination (NOT) per CGP 8.2 to end your coverage under the								
	CGP. This step is independent of the Work Order. Please copy me with the documentation and the EPA's								
	acceptance of the NOT at that time. In the meantime seed and Hydromulch are required per CGP 2.2.14.								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspec	tion Reports		Latest re	oort Date:	?			

Notes:			

New building construction not started. Parking lot complete. Burger King complete by others. Whole foods foundation and north wall under construction by others. No construction equipment or personel were present on this site at the time of inspection.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-803-6155)

jhughes@cabq.gov