

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. H18E					McDonald's 30-0001		
NPDES Id. No. NMR10		11111			5900 Menaul Blvd NE		
12/14/2023		Owner McDonald's USA, LLC			Contractor		
Operator Contact name & title		Alex Breeden			Barnsley Construction Ray Casias		
e-mail		alex.breeden@us.mcd.com			rayc@barnsleyconstruction.com		
Contact Phone #		630-207-0289			505-856-5576		
COA Inspector		Chancellor English			Start/End Time: 1:30pm		
Construction Phase:		<u> </u>					
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up
Weath	er at time of i	nspection?	Cloud	y	Temper	ature: ~	45
Estimated	date of last s	torm 0.25" ი	or greater			12/14/2023	
Item	Deficiency/ Corrective Action						
Number							
1	The self-inspection reports are missing both of the operators' signatures in violation of CGP Part 4.7.2.						
	The modified SWPPP map showing the new construction exit location is missing certification of the						
	operators in violation of CGP Part 7.4.3 Required mitigation: Each inspection report and SWPPP						
	modification must be signed by the operator's signatory in accordance with CGP Appendix G, Part G.11.						
	You must also maintain records showing the dates of all SWPPP modifications which must include the						
	name of the person who authorized each change per CGP Part 7.4.2. Please note that the Delegation of						
	Authority to sign inspection reports and SWPPP modifications cannot be to a third party, and must be a						
	representative	of each oper	ator.				
2	Track-out - Sediment has been tracked-out of the site in violation of CGP Part 2.2.4. Required						
_	mitigation: Implement additional track-out controls as necessary to ensure that sediment removal						
	occurs prior to vehicle exit, and where sediment has been tracked-out from your site onto paved roads,						
	sidewalks, or other paved areas outside of your site, removed the deposited sediment by the end of the						
	same business day in which the track-out occurs, as per CGP Part 2.2.4.						
2.1	Discharge off site?	(Y/N)	no				
4		tion Reports		Latest rei	oort Date:	12/11/2	2023
	Jen mapee	пон перопіз	163	Latestie	oore Bate.	12/11/2	.023
Notes:							
Previous inspections found Posting missing, SWPPP missing, gaps in perimeter wattles							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Chancellor English (505) 924-3325