# **Enterprise Builders: US Eagle FCU Menaul**



### **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 07-07-2021 Time: 11:48 AM

Permit Tracking #: NMR1003M3 Inspector Name: Mario Alderete Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 05-31-2021 .5

Thunderstorms (Isolated)

#### **Construction Time Line:**

Action	Start Date	Date Complete
Initial BMP Installation	04-21-2021	04-28-2021
Clearing and Grubbing	04-21-2021	
Utility Installation		
Construction of Structure		
Final Stabilization		

#### Site Walk

Site wark.				
Question	Yes	No	N/A	Comment
Is there a proper posting sign?	X			
Are areas that have been disturbed, but not under construction been properly stabilized?	$\boxtimes$			
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence	$\boxtimes$			
Wattles/Filter Sock		$\boxtimes$		
Inlet Protection			$\boxtimes$	
Cut Back Curbs			$\boxtimes$	
Waste Management			$\boxtimes$	
Vehicle Tracking Control	$\boxtimes$			
Material Storage		$\boxtimes$		
Dust Control	$\boxtimes$			
Street Sweeping	$\boxtimes$			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points			$\boxtimes$	
Sanitary Stations	X			
Stockpiles	$\boxtimes$			
Other			$\boxtimes$	

## **Enterprise Builders**

# **Enterprise Builders: US Eagle FCU Menaul**

### NMR1003M3

#### **SWPPP Information:**

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	$\boxtimes$			Construction trailer
Was the SWPPP updated at the time of the inspection?	$\boxtimes$			
Are all certification pages signed?		$\boxtimes$		Owners certification has not been signed
Are inspector qualifications in the SWPPP?			$\boxtimes$	
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?	$\boxtimes$			
Was the last inspection/CAL certified?	$\boxtimes$			
personnel properly gathered and evaluated the information subn	nitted. Bas ne best of r	ed on my i ny knowle	inquiry of the	direction or supervision in accordance with a system designed to assure that qualified the person or persons who manage the system, or those persons directly responsible lief, true, accurate, and complete. I am aware that there are significant penalties for attions."
Owner: US Eagle FCU				

 Name
 Signature
 Date

 Operator:
 Name
 Signature
 Date

**Additional Comments:** 

### **Enterprise Builders**

## Enterprise Builders: US Eagle FCU Menaul





Action Log:

Additi Logi							
Location	Action Type	Action Required	Date Noted	Date Completed	Initials		
South west corner		Need to repair sw corner, ground level inside the site is higher than the ground level on the outside	07-07-2021				
Construction trailer	Corrective Action	Fuel storage needs to be off the ground to prevent spills	07-07-2021				

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Mario Alderete / Mario Alderete / 07-07-2021

Name Signature Date



Site Walk Deficiency Photos - Construction trailer





4/28/21





6/2/21





6-23-21



7/7/21