

General Permit SWPPP Inspection

Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information**Inspector's Qualifications**

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

☒ **Regular** ☐ During storm event

☒ **Post-storm event**

Weather Information**Last Storm Event Information**

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

☒ **Clear** ☐ Cloudy ☐ Rain ☐ Sleet

☐ Snowing ☐ High Winds ☐ Partly Cloudy

Have any discharges occurred since the last inspection?

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

If yes, where is it located?

Representative weather site is used to measure precipitation.

Has the Rain Event Page been filled out?

Are there SDS sheets on site?

If yes, where are they located?

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

Date Construction Resumed

Measures Taken to Stabilize the Site:

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

General Permit SWPPP Inspection			
Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Installed BMPs

Completed

Started:

Completed:12/2023

Site Clearing and Grading

Started:

Completed:

Installing Utilities

Started:

Completed:

Building Structure

Started:

Completed:

Paving and Walks

Started:

Completed:

Final Grading/Stabilize Site

Started:

Completed:

Other

Started:

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Stabilized construction entrance, silt fence, inlet protection

Are all of the above controls installed?

YesNo

Do any of the above controls need maintenance?

YesNo

If any of the controls have not been installed or require maintenance, please list the control and explain.

Are the BMPs shown on the map?

YesNo

Were there any changes to the SWPPP?

YesNo

Has the SWPPP been updated?

YesNo

General Permit SWPPP Inspection

Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Were the changes to the SWPPP implemented within 7 days?

☒ Yes ☐ No

List any new BMPs needed:

No new BMP's needed at this time.

Notes:

Delegation letters need to be signed and put them in the book The past inspections they need to be put in the book. Need to put inspector qualifications in the swppp book Need to put updated NOI in the swppp book, and put the updated stormwater team page in the swppp book.

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☐ No ☐ N/A

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

5. Are storm drain inlets properly protected?

Implemented?

☒ Yes ☐ No ☐ N/A

Maintenance Required?

☐ Yes ☒ No ☐ N/A

6. Is the construction exit preventing sediment from being tracked into the street?

General Permit SWPPP Inspection

Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Implemented?

Maintenance Required?

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

Maintenance Required?

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

Maintenance Required?

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

Maintenance Required

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

Maintenance Required?

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

Maintenance Required?

12. Has the Site map been updated to reflect current conditions?

Implemented?

Maintenance Required?

13. Is the NOI posted?

Implemented?

Maintenance Required?

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

General Permit SWPPP Inspection

Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Implemented?

Yes	No	N/A
-----	----	-----

Maintenance Required?

Yes	No	N/A
-----	----	-----

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes	No
-----	----

Have there been any reportable quantities releases of hazardous materials?

Yes	No
-----	----

Additional Notes

No construction activities at the time of inspection. Still under bidding phase.

Certification & Signatures

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X ***Marcos Valadez***

Date

December 15, 2023 at 3:05:38 PM MST

Title

Inspector

General Permit SWPPP Inspection			
Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Photos




General Permit SWPPP Inspection

Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

Weather History



Precipitation
Recorded



No
Precipitation



Missed or data
unavailable

September

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.

General Permit SWPPP Inspection			
Site Name:	<u>Starbucks - Wyoming</u> <u>1914 Wisconsin St NE, Albuquerque, NM 87110</u>	Inspector:	Marcos Valadez
Permit #:	NMR10055D	Inspection Frequency:	Bi-weekly -
Date of Visit:	Dec 15, 2023, 2:25:15 PM	Last Rain Event --	Last Precipitation -- 48h Forecast 1% Chance of Rain

There Are No Action Items