



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	H20E003E	Project Name:	Starbucks Albuquerque		
NPDES Id. No.	NMIR10055D	Location:	2004 Wyoming		
8/28/2024	Owner	Contractor			
Operator	WFC Wyoming NM LLC	Hart Design and Construction			
Contact name & title	Renaldo Gallagher	Andy Hart			
e-mail	rgallagher@westfin.com	ahart@construction.net			
Contact Phone #	770-344-8962	505-345-4001			
COA Inspector	Chancellor English	Start/End Time:	1:30pm		
Construction Phase:	verticals, utilities				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up
Weather at time of inspection?	Cloudy		Temperature: ~	80	
Estimated date of last storm 0.25" or greater	1/21/2024				

Item Number	Deficiency/ Corrective Action				
1	None				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	8/13/2024	

Notes:

SWPPP is located in the Conex Box.

The Delegation of Authority is missing a signature.

City of Albuquerque Stormwater Inspector Signature and date: 8/29/2024
 Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov *Chancellor English*