Bradbury Stamm-Janet Kahn Phase 2



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 10-24-2023 Time: 1:05 PM

Permit Tracking #: NMR1004E6 Inspector Name: John Paiz Qualifications: Inspector Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 09-12-2023 0.56"

Overcast, no precipitation at time of inspection

Construction Time Line:

Action	Start Date	Date Complete					
Initial BMP Installation	01-12-2022	01-12-2022					
Clearing and Grubbing	01-17-2022	01-20-2022					
Utility Installation	04-06-2022						
Construction of Structure	05-24-2022						
Final Stabilization							

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?	\boxtimes			Any disturbed areas need to be stabilized within 14 days of inactivity
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence	\boxtimes			
Wattles/Filter Sock		\boxtimes		
Inlet Protection	\boxtimes			
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control		\boxtimes		
Material Storage	\boxtimes			
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.		\boxtimes		
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			Actively used
Other	\boxtimes			

Bradbury Stamm

Bradbury Stamm-Janet Kahn Phase 2

NMR1004E6

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	\boxtimes			
Was the SWPPP updated at the time of the inspection?	X			
Are all certification pages signed?	\boxtimes			
Are inspector qualifications in the SWPPP?	\boxtimes			
Is there a copy of the NOI and Acknowledgement letter?	\boxtimes			
Is there a delegation letter in the SWPPP?	\boxtimes			
Was the last inspection/CAL certified?	X			

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Albuquerque Public Schools	$U \vdash$	10-27-2023				
	Name	Signature	Date				
Operato	Operator: Darren Mortensen						
	Name	Signature	Date				

7-

Additional Comments:

Bradbury Stamm-Janet Kahn Phase 2

10-24-2023

Date



Name

Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
South perimeter along Indian school	Maintenance		10-24-2023		
Main entrance	Maintenance		10-24-2023		
Indian school	Maintenance		10-10-2023		
South perimeter near New retaining wall	Maintenance		10-24-2023		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: John Paiz

Signature



Site Walk Deficiency Photos - Main entrance

Site Walk Deficiency Photos - Indian school



Site Walk Deficiency Photos - South perimeter near New retaining wall



