Bradbury Stamm-Janet Kahn Phase 2



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 08-15-2023 Time: 3:22 PM

Permit Tracking #: NMR1004E6 Inspector Name: John Paiz Qualifications: Inspector Current Weather Conditions: Clear Date and Amount of Last Recordable Storm Event: 08-08-2023 1.73"

Construction Time Line:

Condition Time Enter							
Action	Start Date	Date Complete					
Initial BMP Installation	01-12-2022	01-12-2022					
Clearing and Grubbing	01-17-2022	01-20-2022					
Utility Installation	04-06-2022						
Construction of Structure	05-24-2022						
Final Stabilization							

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?	X			Any disturbed areas need to be stabilized within 14 days of inactivity
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence			\boxtimes	
Wattles/Filter Sock		\boxtimes		
Inlet Protection	\boxtimes			
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control	X			
Material Storage	\boxtimes			
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.				
Discharge Points	\boxtimes			
Sanitary Stations	X			
Stockpiles	X			Actively used
Other		\boxtimes		

Bradbury Stamm

Bradbury Stamm-Janet Kahn Phase 2

NMR1004E6

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?	\boxtimes			

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Albuquerque Public Schools		
	Name	Signature	Date
Operator	r: Darren Mortensen	DARRIN	08-15-2023
	Name	Signature	Date

Additional Comments:

Bradbury Stamm-Janet Kahn Phase 2



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Parsifal	Maintenance	Replace missing perimeter control	07-18-2023		
North perimeter	Maintenance	Replace missing perimeter controls.	08-01-2023		
Parcifal	Maintenance	Street needs to be cleaned due to sediment track out	08-09-2023		
Indian school	Maintenance	Dirt ramp needs to be removed	08-01-2023		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: John Paiz 08-15-2023

Name Signature Date