City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	H21E020	Project Name:	Nusenda Credit Union
NPDES Id. No.	NMR1005OR	Location:	2801 Juan Tabo Blvd NE

8/28/2024	Owner	Contractor
Operator	Nusenda Federal Credit Union	Enterprise Builders
Contact name & title	Tim Wright	Darren Lewis
e-mail	twright@nusenda.com	dlewis@ebnm.com
Contact Phone #	505-796-2806	505-263-3951
COA Inspector	**Chancellor English**	Start/End Time: 3pm
Construction Phase:	verticals, utilities	

Type of Inspection:		Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up

Weather at time of inspection?	cloudy	Temperature: ~	80
Estimated date of last storm 0.25" or greater		7/27/2024	

Item Number	Deficiency/ Corrective Action			
1	SWPPP - The self-inspection reports need to be signed by both operators in violation of CGP Part 4.7.2. Required mitigation: Each inspection report must be signed by the operator's signatory in accordance with CGP Appendix G, Part G.11.			
2.1	Discharge off site? (Y/N)	no		
4	Self Inspection Reports	Requested	Latest report Date:	8/27/2024

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: 8/30/2024

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English