

### **Storm Water Compliance Inspection Form**

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 05-21-2024 Time: 3:02 PM

Permit Tracking #: Inspector Name: John Paiz Qualifications: Inspector

Owner - NMR1005OR / Operator NMR100Q0

Current Weather Conditions: Clear Date and Amount of Last Recordable Storm Event: 05-16-2024 0.30"

#### **Construction Time Line:**

Action	Start Date	Date Complete				
Initial BMP Installation	08-21-2023	08-22-2023				
Clearing and Grubbing	08-22-2023					
Utility Installation						
Construction of Structure	11-07-2023					
Final Stabilization						

#### Site Walk

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	$\boxtimes$			
Are areas that have been disturbed, but not under construction been properly stabilized?	$\boxtimes$			Any disturbed areas need to be stabilized within 14 days of inactivity
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.				
Silt Fence	$\boxtimes$			
Wattles/Filter Sock		$\boxtimes$		
Inlet Protection	$\boxtimes$			
Cut Back Curbs			$\boxtimes$	
Waste Management	$\boxtimes$			
Vehicle Tracking Control		$\boxtimes$		
Material Storage			$\boxtimes$	
Dust Control	$\boxtimes$			
Street Sweeping	$\boxtimes$			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	$\boxtimes$			
Discharge Points	$\boxtimes$			
Sanitary Stations	$\boxtimes$			
Stockpiles	$\boxtimes$			
Other			$\boxtimes$	

### **Enterprise Builders**

## **Nusenda Credit Union**

Enterprise Builders - Owner - NMR1005OR / **Operator NMR100Q0** 

#### **SWPPP Information:**

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?				
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?				
Is there a copy of the NOI and Acknowledgement letter?				
Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?			$\boxtimes$	

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Owner:	Nusenda Federal Credit Union						
	Name	Signature	Date				
Operator: Chris Vega							
	Name	Signature	Date				

#### **Additional Comments:**

## **Enterprise Builders**

## **Enterprise Builders - Nusenda Credit Union**

# Owner - NMR1005OR / Operator NMR100Q0



Action Log:

Action Log.										
Location	Action Type	Action Required	Date Noted	Date Completed	Initials					
South perimeter	Maintenance	Perimeter controls require maintenance	05-07-2024							
Main entrance	Maintenance	Rock pad needs to be refreshed due to sediment track out	05-21-2024							

<sup>&</sup>quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: John Paiz 05-21-2024

Name Signature Date





