

ALBUQUERQUE.GOV



City of Albuquerque
Planning Department

Stormwater Control Permit for Erosion and Sediment Control

Project Title 12412 Los Arboles NE Albany, NM (single infiltration)

Project Location (Major Cross Streets/Arroyo or address)

Candelaria / Tramway

Property Owner: (or authorized agent provided in writing)

eNOI Number: C 1 are

Attach 2012 Construction General Permit eNOI Detail sheet.

Property Owner: Lee Thompson

Site Contact Name Lee Thompson

Site Contact Phone (505) 480-2272

Site Contact e-mail C.Kahles@msn.com

Applicant: Print Name Lee Thompson

Date 10/3/16

For City personnel use only:

Check boxes if plans/permit are approved:

NA ☒

ESC Plan

☒

Grading Plan

ZONE X UNSHADED

☐

Flood Plain Permit (strike if not required)

The Project is approved for grading (enter date): 10/4/2016

City Personnel Printed Name: Abriel Carrillo

(Rev January 2016)

Did not need to be permitted

cc 11-9-17



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name and Location	Residential 12412 Los Arboles NE		
Site Contact Name & Agency	Lee Thompson Self	Contact Phone #/ E-mail	ckohler@msn.com
Date of Inspection	10-31-16	Start/End Time	1:15/1:35
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One		
Describe Present Phase of Construction	Grading, removing debris		
Type of Inspection:	☒ Regular ☐ During storm event ☐ Post-storm event (> 0.5 inch) ☐ 311 / Complaint Response ☐ Follow-Up		

Weather Information

Weather at time of this inspection? ☐ Clear ☒ Cloudy ☐ Rain ☐ Sleet ☐ Fog ☐ Snowing ☐ Windy	Temperature: ~ <u>70</u> °F
Has there been a storm event since the site was Permitted? ☐ Yes ☒ No	
Amount: ☐ < 1/4" ☐ 1/4" to 3/4" ☐ > 3/4" ☐ Snow _____	

Erosion & Sediment Control Inspection

- Entrance / Track-Out medium track-out - owner agreed to sweep
- Sediment Controls / Silt Fence, Check Dams, Waddles, etc. none - owner proposed and agreed to grade a swale to direct drainage to the south to a low area
- Erosion Controls / Mulch, Seed, _____
- Housekeeping/Pollutant Controls OK
- Debris/Pollutants/Sediment in MS4 NO
- Notes Spoke to owner "RT" first time
owner was a nice guy

 Is site being maintained in compliance with the Drainage Ordinance? • Yes • ☒ No

 Signature Curtis Cherne

 Date 10-31-16