NOTE: 2016 Protocol - Maximum of one SSWR per permit

PROPRIETARY COMPANY MATERIAL



Date & Time: 10-21-2019 at 11:50 AM

NATIONAL STORM WATER QUALITY PROGRAM SITE INSPECTION REPORT (SIR)

For use on most PulteGroup Sites as of 01/01/2016

Commu	nity Name:	Pulte: Inspiration, Arr	oyo Vista Blvd and Mesa Drive,	Albuquerque, NM 87120 NPDI	ES: NMR10024T	
		(Include Site Name, Ci	ty, State, Zip Code and NPDES/	Construction Storm Water Pern	nit Number)	
Master 5	Site List ID:	A1414	Ins	spection performed by: Tim Sla	tunas, CISEC, Green Globe Env	ironmental
				(Print N	lame, Company, and Title / Qual	ifications)
Stages	of Construction:	(check all that apply)	X Land Development	Inactive	Vertical Construction	Post-Construction
			Land and Vertical			
Type of	Inspection:	(check all that apply)	Routine Inspection	Storm-Event Related	Final Site Inspection	
J 1	•	11 37	Other:			
I.	SWPPP - Respon	d to all Questions				
Item	•	•			Yes	<u>No</u>
A	Was the SWPPP accessible at the time of the inspection?		tion?			If "No," then an Action Item is required.
В	Is the SSWR correct	ly identified in the SWPPP?				Ttem is required.
С	Does the SWPPP ref	flect the current stage of develor	oment?		\boxtimes	Describe all Action Items on the reverse side of this
D	Have all SIR action	Items identified on the precedin	g reports been resolved?			sheet. (Section IV)
E	Is NSQP Signage po	osted and in compliance with N	SQP requirements?		\boxtimes	
II.	Estimated date of	most recent Storm Event Th	at triggered an Inspection:10) <u>-04-2019</u>		
	Provide rainfall info	ormation as required by the App	licable Permit: <u>.25 Inches</u>			e storm-event related Inspection required by the Applicable Permit)
III.	Site BMP Inspect	ion	Not			
<u>Item</u>	SWPPP Items		<u>Applicable</u>	<u>Acceptable</u>	Action Item	Assigned To
Erosion	1 Control					
1	Protection of Distur	rbed Areas		\boxtimes		
2	Slope Protection		\boxtimes			
3	Vegetation / Revege	etation	$\overline{\boxtimes}$			
4	Velocity Reduction	Devices / Outlet Protection		\boxtimes		
Sedime	ent Control					
5	Check Dams (rock,	gravel, other)		\boxtimes		
6	Silt Fence				\boxtimes	Pulte
7	Berms, Dikes, Straw	Wattles	П	\bowtie	П	
8	Detention Basins/S	ediment Traps		$\overline{\boxtimes}$		
9	Stockpiles Protected	d/Stabilized		\boxtimes		
10	Storm Water Inlet Pr	rotection	\boxtimes			
Housel	keeping / Trade Con	npliance				
11	Waste and Trash Ma	anagement		\boxtimes		
12	Spill and Leak Prev	ention				
13	Sanitary Stations			\boxtimes		
14	Concrete and Const	ruction Washouts	\boxtimes		<u> </u>	
15		tential Contaminate Storage		\boxtimes	<u> </u>	
16	Equipment Storage	and Maintenance			□ .	
17	Construction Exits	and Entrances			\boxtimes	Pulte
18	Dust Control			\boxtimes		
19	Street Sweeping			\boxtimes		

PROPRIETARY COMPANY MATERIAL

Not <u>Item</u> SWPPP Items (continued) **Applicable Acceptable Action Item** Assigned To Other 20 Non-Storm Water Flow 21 Site's Weathering of Storm Events 22 Site Discharge Points 23 BMP Provider Performance $\overline{\nabla}$ 24 IV. **Action Items** V. Responsive Action Completion Location and Responsive Action to be taken **Date Noted Date of Completion** Item **Initials** Deficiency Name: North and East Perimeter 10-21-2019 Corrective Action: Need to stand up and remove the built up sediment on the silt fence Deficiency Name: VTC

Attach additional sheet(s) of SIR addendum if necessary

Corrective Action: Need to refresh the VTC

17

SIR must be reviewed and signed below by SSWR - Not Delegable: I certify under penalty of law that Sections I-V of this document and all attachments were prepared by me or under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. In the event there are no Action Items in this report that have remained unresolved for a period in excess of that allowed by the Applicable Construction General Permit, I further certify under penalty of law that this Site is in compliance with the SWPPP and the Applicable Construction General Permit. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations. Certification applies to the area under the supervision of the SSWR signing this report.

10-07-2019

Certified By: (SSWR - Must be a PulteGroup Employee)		Certified By: (Third Party Inspector if required by the Applicable Permit)		
Brian Anderson		Tim Slatunas		
Site Storm Water Representative - Print Name and Title		Inspector - Print Name		
Site Storm Water Representative Signature (Use Ink)	Date	Inspector Signature (Use Ink)	Date	

VI. Justification for non-completion of Responsive Actions

Describe why any Responsive Actions were not corrected within the permit required time period (if applicable).

N/A

Attach additional sheet(s) if necessary