

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Fed Ex Brunacini Warehouse					
Location:		7601 Los Volcanes Rd					
Site Contact Name &		John Trujillo -		ESC File No.		J10E002G	
Agency		jtrujillo@br		NPDES Id. No.		NMR100YX	
Inspection Date:				240/1330hrs			
	water Inspecto	r: 1	Γimothy E. Sims				
	tion Phase:	site work and vertical					
Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up							
\A/ + l-			Cla		T		02*
	er at time of it date of last s		Cle	ar	rempe	erature: ~	93*
Estimateu	uate of last s	101111 0.25	n greater			5/11/2019	
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	Washout is on the NE area of site. Please clean and remove washout. Have trades use washout						
	facility						
2	Construction and domestic waste not in acceptable waste container. Please mitigate and have						
	workers utilize provided waste containers.						
3	Please provide a sediment BMP on the west entrances (Gallatin)						
4	The stock pile on the SW corner of site will require a sediment BMP on the downhill side.						
	Please provide a sediment BMP.						
			_	_			
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports		Latest rep	ort Date:	06.13.	19
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

06.27.19