

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Fed Ex Brunacini Warehouse						
Location:	7601 Los Volcanes Rd						
Site Contact Name & Agency	John Trujillo - Brunacini	ESC File No.	J10E002G				
	jtrujillo@brunacini.com	NPDES Id. No.	NMR100YX				
Inspection Date:	07/08/19	Start/End Time:	1400/1500hrs				
CoA Stormwater Inspector:	Timothy E. Sims						
Construction Phase:	site work and vertical						
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	x	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	89*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
1	Washout is on the NE area of site. Please clean and remove washout. Have trades use washout facility		
2	Construction and domestic waste not in acceptable waste container. Please mitigate and have workers utilize provided waste containers.		
3	Please provide a sediment BMP on the west entrances (Gallatin)		
4	The stock pile on the SW corner of site will require a sediment BMP on the downhill side. Please provide a sediment BMP.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 06.13.19

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/08/19