



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Fed Ex Brunacini Warehouse		
Location:	7601 Los Volcanes Rd		
Site Contact Name & Agency	John Trujillo - Brunacini jtrujillo@brunacini.com	ESC File No.	J10E002G
		NPDES Id. No.	NMR100YX
Inspection Date:	07/19/19	Start/End Time:	0800/0830hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	site work and vertical		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	75*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 07/11/19 (reports onsite)

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/19/19