



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Ben E. Keith				
Location:	601 Gallatin Pl. NW				
Site Contact Name & Agency	Thomas Hays - ESI Constructors	ESC File No.	NMR10023X		
	thays@esigroupusa.com	NPDES Id. No.	J10E002G1		
Inspection Date:	01/16/20	Start/End Time:	1050/1100hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	earthwork				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Snow	Temperature: ~	45*
Estimated date of last storm 0.25" or greater	11/22/2019		

Item Number	Deficiency/ Corrective Action			
	no issues observed with this inspection			
	***Please send me the latest SWPPP self-inspection report			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	11/14/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/16/20