

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Ben E. Keith									
Location:		601 Gallatin PI NW		ESC File No.		J10E002G1		NPDES Id. No.		NMR10023X	
Site Contact Name & Agency		A. Mark Gehl- ESI		Phone: (o)		262-369-3535					
		mgehl@esigroupusa.com		Phone: (m)		262-510-3089					
Owner		Roy Markham - Ben E. Keith		Phone: (o)		817-759-6840					
Owner's e-mail		rlmarkham@benekeith.com		Phone: (m)							
Inspection Date:		07/21/20		Start/End Time:		0755/0810hrs					
CoA Stormwater Inspector:				Timothy E. Sims							
Construction Phase:		Vertical									
Type of Inspection:	x	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	73*
Estimated date of last storm 0.25" or greater	6/1/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection.		
	New field construction manager, Mark Gehl, discussed relocating north and east perimeter sediment BMP to allow for future construction. SWQ understands and agrees with this relocation.		
	ESI to ensure SWQ and General permit program requirements are met by means as directed by field conditions.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 7/8/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/21/20