

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Ben E. Keith					
Location:		601 Gallatin Pl. NW					
Site Contact Name & Agency	Roy Markham - Ben E Keith			ESC File No.	NMR10023X		
	rlmarkham@benekeith.com			NPDES Id. No.	J10E002G1		
Inspection Date:	09/12/19	Start/End Time:	1015/1025hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		earthwork					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	75*
Estimated date of last storm 0.25" or greater	9/11/2019		

Item Number	Deficiency/ Corrective Action			
1	Please provide the NPDES posting for this site.			
2	Please ensure the spill kit is on site.			
3	Please provide the SWPPP booklet onsite.			
4	Track out is being swept daily. Thanks, please ensure to maintain this BMP.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	no report on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 09/12/19