



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	J10E002G1	Project Name:	Ben E. Keith		
NPDES Id. No.	NMR10023X	Location:	601 Gallatin Pl. NW		
4/26/2021	Owner	Contractor			
Operator	Ben E. Keith	ESI			
Contact name & title	Roy Markham	Mark Gehl			
e-mail	rmarkham@benekeith.com	mgehl@esigroupusa.com			
Contact Phone #	817-759-6840	262-510-3089			
COA Inspector	Thomas Evans	Start/End Time:	11:30 AM/12:00 PM		
Construction Phase:	Landscaping				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint	
Weather at time of inspection?		clear	Temperature: ~	74	
Estimated date of last storm 0.25" or greater		2/22/2021			
Item Number	Deficiency/ Corrective Action				
1	No posting of NPDES permit				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:		

Notes:	Crew was pouring rock on the remaining disturbed area on the west side of the site.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 04/26/2021