

## **INSPECTION REPORT**

## **GENERAL INFORMATION**

DATE OF INSPECTION:	5/21/2020			
COMPANY NAME:	Ben E. Keith			
PROJECT NAME:	Ben E. Keith Food Distribution Facility			
LOCATION:	601 Gallatin Place NW,Albuquerque,New Mexico,87121			
TRACKING NO:	NMR10023X			
COMPLIANCE EVALUATION:	Satisfactory			
TYPE OF INSPECTION:	14Day			
START TIME:	11:10 AM			
END TIME:	11:35 AM			
INSPECTOR'S NAME:	Diana Baltazar			
INSPECTOR'S TITLE:	NPDES Inspector			
INSPECTOR'S QUALIFICATIONS:	StormwaterONE No: 6f93e116			
INSPECTOR'S CONTACT:	505-379-2445			
PHASE OF CONSTRUCTION:	<ul> <li>□ Clear and Grub ✓ Excavation ✓ Building (vertical)</li> <li>□ Rough Grading □ Infrastructure □ Final Grading</li> <li>□ Final Stabilization</li> </ul>			
WEA	WEATHER INFORMATION			

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	75	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	рното
1	Silt Fence	None	None	Perimeter	7400	LF	Yes
2	Construction Entrance	None	None	Fortuna Road Entrance	1	EA	
3	NPDES Permit Notification	None	None	Fortuna Road Entrance	1	EA	

## **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	• Yes ONo ON/A	Yes No	
2	Are steep slope areas not actively being worked properly stabilized?	• Yes No N/A	Yes No	Slopes are currently stable and compact
3	Are disturbed areas not actively being worked properly stabilized?	• Yes ONo ON/A	Yes No	Currently being worked on
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	• Yes ONo ON/A	Yes No	Silt fence surrounding site is stable. Permanent structures have been installed on South End
5	Are discharge points and receiving waters free of any sediment deposits?	• Yes ONo ON/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	Yes No	Dumpster on site, site to be clean by the end of each day
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	● Yes ○ No ○ N/A	Yes No	Washout station should be hauled off site once full of concrete debris
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes ONo ON/A	Yes No	
10	Are offsite flows entering the construction site?	Yes ● No N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	○Yes ● No ○ N/A	○Yes • No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	• Yes ONo ON/A	Yes No	
13	Are non-stormwater discharges properly controlled?	● Yes ○ No ○ N/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	● Yes ○ No ○ N/A	Yes No	In compliance
15	Are changes to the SWPPP necessary at this time?	Yes No N/A	Yes No	
16	Are dust control measures being properly implemented?	• Yes ONo ON/A	Yes No	Watering trucks active on site
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	Yes No	

#### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Diana Baltazar	DATE:	May 22, 2020
SIGNATURE AND AFFILIATION:			

#### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	DATE:
SIGNATURE:		