



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	7601 Los Volcanes				
Location:					
Site Contact Name & Agency	John - Brunacini abrunacini@brunacini.com	ESC File No.	J10E002G2		
		NPDES Id. No.	NMR1001YX		
Inspection Date:	02/24/20	Start/End Time:	1300/1330hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	earthwork				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Snow	Temperature: ~	50*
Estimated date of last storm 0.25" or greater			

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection.		
	Please provide latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: not on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 02/24/20