| NPDES | Tracking | No: | |
|--------------|-----------------|------|--|
| 112 222 | | 2.00 | |

ECS File: 7/0E 643



City of Albuquerque Stormwater Construction Site Inspection Report

| | General Information | | | |
|---|--|-------------------|--------------------|--|
| Project Name and Location | Glenrio Apartments Glen Rio and 72nd Casey Cumeron Parillin Construction | ESC PERMIT # | M | |
| Site Contact Name & Agency | Casey Cumeron Pavillin Construction | Contact Phone # | 565-330-4587 | |
| Date of Inspection | 6-5-15 | Start/End Time | | |
| Inspector Name, COA Dept. | Curtis Cherne, Stormwater Quality | | | |
| Inspector Phone / E-mail | 505-924-3420/ccherne@cabq.gov | | | |
| Inspector Qualifications | Stormwater USA | | | |
| Describe Present Phase of Construction | 5, te Complate - St-b. lizis | | | |
| Regular | Random • During storm event • Post-sto | rm event • 311/ | Complaint Response | |
| | Weather Information | | | |
| Has there been a storm event s | Rain · Sleet · Fog · Snowing · since the site was Permitted? · Yes · No | High Winds · Ot | | |
| Amount: • < 1/4" • 1/4" to 3 | 34" • > 34" Intensity: • Light • M | | • Snow | |
| Check any BMPs that he Entrance / Off Tracking | Erosion & Sediment Control Inspe | | | |
| Sediment Controls / Silt I Check Dams, Waddles | Fence, | | | |
| Erosion Controls / Mulch | ı, Seed, | | | |
| Wind Blown Erosion | <i>N</i> • | | | |
| Housekeeping / Pollutant | | | | |
| | ance with Const. Gen. Permit ?" (es)" No | Cuto Ch | 6-5-15 | |
| 10 one comp mannamed in compile | | Signature | Date | |