

City of Albuquerque Stormwater Construction Site Inspection Report

			General in	ioiiiatioii				
Project Name: 7301 Los Volcanes								
Location:		Lot North of 7	401 Los Volcanes					
Site Cont	tact Name &	Angelo B.		ESC File No.		J10E048		
Agency		Owner		NPDES Id. No.		NMR1002UH		
Inspection	Date:		tart/End Time: 11	10/1120hrs				
	water Inspecto	r:	Timothy E. Sims					
Construction Phase:				earthwork				
Type of Inspection:		Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint x	Follow Up	
Weather at time of inspection? Cloudy Temperature: ~ 56*							56*	
<u>Estimated</u>	date of last s	<u>torm 0.25" o</u>	r greater					
Item								
	Deficiency/ Corrective Action							
Number								
	All previous iss	sues, no new is	ssues observed wi	th this inspec	ction			
0.4		6.6.3	T	ı				
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	tion Reports		Latest rep	ort Date:	3/13/20	20	
			•	•	•			
Notes:								
110103.								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

03/30/20