



City of Albuquerque
Stormwater Construction Site
Inspection Report

General Information

Project Name and Location	Bosque Antigua 719 Gabaldon Dr		
Site Contact Name & Agency	Scott Ashcraft Adam Romero Las Ventanas Homes	ESC File No. NPDES ID No.	312E015 NMR100106
Date of Inspection	12-10-18	Start/End Time	12:10 / 12:38
COA Inspector Name	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	graded		

Type of Inspection:

☒ Regular • During storm event • Post-storm event (> 0.25 inch) • 311 / Complaint Response • Follow-Up

Weather Information

Weather at time of this inspection?

Temperature: ~45 F°

• Clear • ☒ Cloudy • Rain • Sleet • Fog • Snowing • ☒ Windy

Has there been a storm event since the site was Permitted? • Yes • ☒ No

Amount: • < 1/4" • 1/4" to 3/4" • > 3/4" • Snow _____

Inspection

CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
1.5	Post a Notice		
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft		
2.2.3	Sediment control along any perimeter	✓	provide sediment BMP south edge of
2.2.3	Sediment control along any perimeter		draw west end - spoke to owner
2.2.3	Sediment control along any perimeter		wrap corner
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track-out	✓	pad requires maintenance - residents smaller road?

2.2.5	Manage stockpiles		
2.2.6	Minimize Dust		
2.2.10	Protect Storm Drain Inlets		
2.2.10	Protect Storm Drain Inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.3.1	Equipment and Vehicle Fueling		
2.3.2	Equipment and Vehicle Washing		
2.3.3	Building Material Storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and Domestic Wastes		
2.3.3	Construction and Domestic Wastes		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site?	• Yes • No	
4	Self-Inspection Reports	<i>request</i>	Latest Report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within 7 days.

Notes:

City of Albuquerque Stormwater Inspector Signature and Date:

Curtis A. Cherne
Signature

12-18-18
Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov