



City of Albuquerque
Stormwater Construction Site Inspection Report

Date and Time of Inspection: 4-11-19 12:40/1:00
Project Name and Location: Bosque Antigua, 719 Gabaider Dr
Site Contact(s) and Company: Scott Ashcraft, Las Ventanas Hnas, Adam Romero
COA Inspector Name: Curtis Cherne
ESC File No. and Owner NPDES ID NO.: 512EUS, NMR100106
Present Phase of Construction: gravel, idle
Type of Inspection: Regular During Storm Post storm 311/complaint Follow-up
Weather at time of Inspection: cloudy, windy Temp: 55
Estimated date of last storm that required an inspection: 3-12-19

Inspection Deficiencies:

1. Silt fence at entrance requires maintenance

City of Albuquerque Stormwater Inspector Signature and Date:

Curtis C. Cherne
Signature

4-11-19
Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov

Note: ① gusts up to 25 mph. no observed blowing sand/dust
② Bud, a neighbor, spoke to me concerning blowing dust