



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Sawmill Market				
Location:	1901 Bellamah NW				
Site Contact & Agency	Lance - Hart Construction	ESC File No.	J13E017A		
	<a href="mailto:landerson@hartconstruction.net">landerson@hartconstruction.net</a>	NPDES Id. No.			
Inspection Date:	01/08/20	Start/End Time:	12505/1300hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	interior work				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	44
Estimated date of last storm 0.25" or greater	11/21/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 11/22/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 01/08/20