



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Sawmill Market				
Location:	1901 Bellamah NW				
Site Contact Name & Agency	Lance - Hart Construction	ESC File No.	J13E017A		
	landerson@hartconstruction.net	NPDES Id. No.			
Inspection Date:	02/20/20	Start/End Time:	0845/0850hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	STABILIZED				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Temperature: ~ 37*
Estimated date of last storm 0.25" or greater	10/4/2019

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 02/20/20