



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Sawmill Market		
Location:	1901 Bellamah NW		
A	Lance - Hart Construction	ESC File No.	J13E017A
	landerson@hartconstruction.net	NPDES Id. No.	
Inspection Date:	06/17/19	Start/End Time:	1130/1200hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	block work		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	80*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed, all previous issues mitigated		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	Latest report Date:	6/6/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/17/19
