



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Sawmill Market				
Location:	1901 Bellamah NW				
Site Contact & Agency	Lance - Hart Construction	ESC File No.	J13E017A		
	landerson@hartconstruction.net	NPDES Id. No.			
Inspection Date:	10/29/19	Start/End Time:	1410/1440hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	block work				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	91*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 10/25/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 10/29/19