City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Sawmill Market						
Location:	1901 Bellamah NW						
Site Contact & Agency	Lance - Hart Construction			ESC File No.	J13E017A		
	landerson@hartconstruction.net			NPDES Id. No.			
Inspection Date:	11/20/19	Start/End Time:	0920/0925hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:	interior work						
Type of Inspection:	x Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up		

Weather at time of inspection?	Clear	Temperature: ~	53*
Estimated date of last storm 0.25" or greater		10/4/2019	

Item Number	Deficiency/ Corrective Action			
	no issues observed with this inspection			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	11/8/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.11.21 08:30:13 -07'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 11/20/19