

City of Albuquerque Stormwater Construction Site Inspection Report

-						
			General Information			
Project Name and Location		Saumill Market				
		1901 Bellanch NW				
Site Contact Name & Agency		1901 Bullamah NI Lance Anderson Hart Construction		ESC File No. NPDES ID No.	313 E017.A	
		Hart C	onstruction	NFDES ID No.		
Date of Inspection		3-5-	19	Start/End Time	20/11:45	
COA Inspector Name		Curtis Cherne, Stormwater Quality				
Describe Present Phase of Construction		pouring curbs, installing whities				
Type of Ir	spection:	,				
Regu	lar • During storm	event • Post-s	storm event (> 0.25 inch)	311 / Complaint Res	ponse • Follow-Up	
			Weather Information			
~)	at time of this inspection lear • Cloudy • Ra	n?	Fog · Snowing ·	Tem Windy	perature: ~F°	
Has there	been a storm event sin	ce the site was Pe	ermitted? (Yes No			
Amount:	< 1/4" (4" to 3/4"	' > 3/4''	• Snow"			
Mary Charles			Inspection			
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes			
1.5	Post a Notice					
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.4	Minimize sediment track-	-				

2.2.5	Manage stockpiles				
2.2.6	Minimize Dust		= =		
2.2.10	Protect Storm Drain Inlets				
2.2.10	Protect Storm Drain Inlets				
2.2.11	Minimize erosion of conveyance channels				
2.2.12	Sediment Basins				
2.2.14	Stabilize exposed portions of the site.				
2.2.14	Stabilize exposed portions of the site.				
2.2.14	Stabilize exposed portions of the site.				
2.2.14	Stabilize exposed portions of the site.				
2.3.1	Equipment and Vehicle Fueling				
2.3.2	Equipment and Vehicle Washing				
2.3.3	Building Material Storage				
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage				
2.3.3	Construction and Domestic Wastes				
2.3.3	Construction and Domestic Wastes		Armous Liquis concrete spills		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	Numerous Liquis concrete spills		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.				
2.4	Dewatering				
2.1	Discharge off site?	· Yes (No)			
4	Self-Inspection Reports	Meunt	Latest Report Date:		
Notes: (City Inspector Use) Items in compliance can be left blank. Construction General Permit (CGP) Maintenance or corrective actions are to be completed within 7 days.					
Notes:	wallor site u	vl lonce	- Eiscussed Trash & washout/ Spill		

City of Albuquerque Stormwater Inspector Signature and Date:

Signature

Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov