ECS File: 775053



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information		
Project Name and Location	McDungis's oil town central west of Roo Gra	ESC PERMIT #	106
Site Contact Name & Agency	Lee Mornis	Contact Phone #	972-869 -
Date of Inspection	6-24-15	Start/End Time	5:20/10:28
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Stormwater USA		
Describe Present Phase of Construction	Cunstructed / Stab. h Fre		
Regular	Random • During storm event • Post-st Weather Information	torm event • 311/0	Complaint Response
Weather at time of this inspection? Temperature: ~ 65 F°			
	Rain · Sleet · Fog · Snowing		
Has there been a storm event s	since the site was Permitted? Yes No		
Amount: • < 1/4" • 1/4" to	3/4" · > 3/4" Intensity: · Light · N	Med. • Hvy.	• Snow"
	Erosion & Sediment Control Insp	pection	
Check any BMPs that h	ave FAILED or REQUIRE MAINTENANC	<u>CE</u>	
Entrance / Off Tracking	NO		
Sediment Controls / Silt l Check Dams, Waddles	s, etc.		
Erosion Controls / Mulch, Seed, 516121			
Wind Blown Erosion			
Housekeeping / Pollutant	Controls gwn		
			1.64.6
Is site being maintained in compli	ance with Const. Gen. Permit ?" (Yes "No	Signature	C 24-5 Date