



Drainage conditions along 4th Street have been greatly improved as a result of the storm drain system that was recently (1991) constructed as part of the street reconstruction.

## SECTION A

FACILITY			ENGINEER'S SEAL			SURVEY INFORMATION			BENCH MARKS			AS BUILT INFORMATION		
NO.	DATE	REMARKS	BY	NO.	BY	DATE	CONTRACTOR	WORK BY	INSTRUCTIONS	DATE	ACCEPTANCE BY	DATE	REVISION BY	DATE
DESIGN				DESIGNED BY: LEE BELL				DATE: FEB. 1992				DRAWINGS		
DRAWN BY: LEE BELL				DATE: FEB. 1992				CHECKED BY: P. ROYBAL				DATE		
CHECKED BY: P. ROYBAL				DATE: FEB. 1992				REGISTERED BY				DATE		
														
SHEET				OF										