

FIELD REPORT

PROJECT NO.	PROJECT DESCRIPTION	OBSERVER	DATE OBSERVED
	Medical office bldg within R. Pevero		12-1-78
OTHERS PRESENT: 8016 Constitution R. N.E.			

Reason for Field Check:

For the drainage report on this medical center.

Description of Field Check Performed:

There is a ponding area on the north side of the bldg. with a vol. of 2.652 ft³ and 6' 0" dia.

Notes or Conclusions:

Everything is OK going by the approved plan. There is a pond on the west side of the bldg.

Up Action required:

Everything is OK and no followup will be needed.

Date of Field Report to:

CITY:

Albuquerque, N.M.

OBSERVER

William E. Brown