

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Winrock Town Center Phase B					
Location:		Louisiana and Indian School					
Site Contact Name &						J19E058	
Agency				NPDES Id. No.	NMR100282		
Inspection Date:				40/1320hrs			
	vater Inspecto	r: Tir	mothy E. Sims				
Construction Phase:		site work and interior renovations					
Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up							
\A/a-+l-			Clas		T	t	C2*
	er at time of in		Clea	r	rempe	erature: ~	62*
Estimated	date of last's	torm 0.25" or	greater			10/4/2019	
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	Construction and domestic waste not in acceptable container. Please mitigate and ensure trades						
	utilize provided refuse facility.						
2	Washout on north side of building requires mitigation.						
3	Please provide the latest SWPPP self-inspection report.						
2.1	Discharge off site?	(Y/N)	No		ī		
4	Self Inspect	ion Reports	requested	Latest rep	ort Date:	not yet re	ceived
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

10/22/19