



INSPECTIONS PLUS

Winrock Towne Center
TLC Plumbing & Utility Inc.
General Permit SWPPP Inspection



2100 LOUISIANA BLVD
NE
ALBUQUERQUE, NM
87110



Last Rain Event

Monday, February 15, 2021,
0.0"

Last Precipitation

Friday, February 19, 2021,
0.09"

48h Forecast

29% Chance of
Rain

Inspection Date and Time

Mar 12, 2021, 9:59:56 AM

Completed by

Marcos Valadez

Frequency

Bi-weekly -

Permit #

NMR100282 NMR100290

Inspection Form Instructions - Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information

Inspector's Qualifications - Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

Regular

~~During storm event~~

~~Post storm event~~

Weather Information

Last Storm Event Information - For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

~~Clear~~

~~Cloudy~~

~~Rain~~

~~Sleet~~

~~Snowing~~

~~High Winds~~

**Partly
Cloudy**

Have any discharges occurred since the last inspection?

~~Yes~~

☒ **No**

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

~~Yes~~

☒ **No**

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

☒ **Yes**

~~No~~

If yes, where is it located?

At the entrance of the site

Has the Rain Event Page been filled out?

~~Yes~~

☒ **No**

Are there SDS sheets on site?

~~Yes~~

☒ **No**

If yes, where are they located?

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

Date Construction Resumed

Measures Taken to Stabilize the Site:

Gravel and natural vegetation

Construction
Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

~~Not Started~~

~~Started~~

| Completed

Started:

Completed:

Site Clearing and Grading

Started:

Completed:

Installing Utilities

Started:

Completed:

Building Structure

Started:

Completed:

Paving and Walks

Started:

Completed:

Final Grading/Stabilize Site

Started:

Completed:

Other

Started:

Site-specific
BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Stabilized construction entrance, Mulch sock, Pond, roll off, portable toilet

Are all of the above controls installed?

☒ **Yes**

☐ ~~No~~

Do any of the above controls need maintenance?

☐ ~~Yes~~

☒ **No**

If any of the controls have not been installed or require maintenance, please list the control and explain.

Are the BMPs shown on the map?

☒ **Yes**

☐ ~~No~~

Were there any changes to the SWPPP?

☐ ~~Yes~~

☒ **No**

Has the SWPPP been updated?

☒ **Yes**

☐ ~~No~~

Were the changes to the SWPPP implemented within 7 days?

☒ **Yes**

☐ ~~No~~

List any new BMPs needed:

Notes:

Inspecting only the section next to Dillard's.(continue on hold). No issues at the time of inspection.

Oversight Issues

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

☐ ~~Yes~~

☐ ~~No~~

☒ **N/A**

Maintenance Required?

~~Yes~~

~~No~~

| **N/A**

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

4. Are discharge points and receiving waters free of any sediment deposits?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

5. Are storm drain inlets properly protected?

Implemented?

| **Yes**
~~No~~
~~N/A~~

Maintenance Required?

~~Yes~~
| **No**
~~N/A~~

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

| **Yes**
~~No~~
~~N/A~~

Maintenance Required?

~~Yes~~
| **No**
~~N/A~~

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

| **Yes**
~~No~~
~~N/A~~

Maintenance Required?

~~Yes~~
| **No**
~~N/A~~

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

~~Yes~~
~~No~~
| **N/A**

Maintenance Required?

~~Yes~~
~~No~~

| **N/A**

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

~~Yes~~

~~No~~

| **N/A**

Maintenance Required

~~Yes~~

~~No~~

| **N/A**

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

~~Yes~~

~~No~~

| **N/A**

Maintenance Required?

~~Yes~~

~~No~~

| **N/A**

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

~~Yes~~

~~No~~

| **N/A**

Maintenance Required?

~~Yes~~

~~No~~

| **N/A**

12. Has the Site map been updated to reflect current conditions?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

13. Is the NOI posted?

Implemented?

| **Yes**

~~No~~

~~N/A~~

Maintenance Required?

~~Yes~~

| **No**

~~N/A~~

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

~~Yes~~

~~No~~

| **N/A**

Maintenance Required?

~~Yes~~

~~No~~

| **N/A**

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

~~Yes~~

| **No**

Have there been any reportable quantities releases of hazardous materials?

~~Yes~~

| **No**

Additional Notes

Currently they are working on the west side between mattress firm and petsmart (remodeling)

Certification

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X *Marcos Valadez*

Date

March 12, 2021 at 10:31:58 AM MST

Title

Inspector

Photos



image.jpg



image.jpg

Weather History

 Precipitation Recorded  No Precipitation  Missed or data unavailable

February

12 th	0	13 th	0.19"	14 th	0.28"	15 th	0	16 th	0.19"	17 th	0.13"	18 th	0.09"
19 th	0	20 th	0	21 st	0	22 nd	0	23 rd	0	24 th	0	25 th	0
26 th	0	27 th	0	28 th	0								

March

1 st	0	2 nd	0	3 rd	0	4 th	0	5 th	0	6 th	0	7 th	0
8 th	0	9 th	0	10 th	0	11 th	0	12 th	0				

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.

There Are No Action Items