



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	K08E003	Project Name:	West Mesa RV Park		
NPDES Id. No.	NMR1003H4	Location:	Volcano Rd and 102nd St. NW		
5/13/2021	Owner			Contractor	
Operator	S.M. Quraishi			Shakeel Rizvi	
Contact name & title	S.M. Quraishi			Shakeel Rizvi	
e-mail	smquraishi@yahoo.com			shaky1424@yahoo.com	
Contact Phone #	505-379-6643			505-315-6563	
COA Inspector	Thomas Evans	Start/End Time:	2:20 PM/2:45 PM		
Construction Phase:	earthwork				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	clear	Temperature:	~ 79		
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	No inlet protection. Install inlet protection BMPs to prevent sediment from entering the storm drains.				
2	Sediment accumulation in the streets. Sweep trackout and remove sediment daily.				
3	Domestic waste on ground. Remove any construction and domestic waste and place in an approved waste container.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	4/15/2021	

Notes:	Crew was digging up the existing asphalt on the South road.

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215) *Thomas Evans* 05/14/2021
tevans@cabq.gov