

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No. K08E		1 ,		Paradise RV Park Phase 2				
NPDES Id. No.	NMR10				Volcano Rd. and 102nd Street			
8/29/2025		Owner West Mess BV Park, II C		Contractor				
Operator		West Mesa RV Park, LLC Karan Rai						
Contact name & title e-mail		karanveer.rai@gmail.com						
Contact Phone #		760-783-6599						
COA Inspector		James Hughes			Start/End Time:	10am		
Construction Phase:		Phase 2 was graded without approval				oval		
	nspection:	Regular	Storm Event			311/Complaint Follow Up		
Weather at time of					Temperature: ~ 80			
Estimated	date of last s	storm 0.25" or	greater			8/27/2025		
Item			Deficienc	y/ Correctiv	ο Action			
Number			Deficient	y/ Correctiv	e Action			
1	NOI - Phase 2	construction sta	arted one vear as	o without su	bmitting the p	roperty owner's Notice of		
_			-					
	Intent and ESC Plan to the City for approval. The NOI and ESC Plan you submitted on 8/27/25 had man deficiencies sent to you yesterday that must be addressed before the NOI and ESC Plan can be							
	approved. <b>Required Mitigation:</b> The property owner's NOI and ESC Plan must be submitted to the City							
	of Albuquerque for review and approval per Albuquerque's Erosion and Sediment Control (ESC) ordinance § 14-5-2-11(A).							
						5.16		
2		=			_	no Rd from stormwater		
	crossing 102 <sup>nd</sup> St. adjacent to this site, but the Phase 1 pond was filled one year ago during the							
	unauthorized start of the Phase 2 earthwork. The Phase 2 block wall along 102 <sup>nd</sup> St. further contribute							
	to the diversion of 102 <sup>nd</sup> St. stormwater to the recent erosion that occurred in Volcano Rd and city Pon							
	NE2 south of your site in violation of city Ordinance § 14-5-2-12(B)(3). Required mitigation: Either							
	restore the Ph	ase 1 Pond and	the onsite swale	or construct	alternative BM	1Ps in accordance with an ESC		
	Plan approved	l by the City SW	Q Section until co	onstruction a	nd stabilization	n are complete in the City's		
			tablish onsite BM					
		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		о рег алгар	p. 0 . 0			
	Codimont Th	is site bas dissu	ntod the draines	a nattara inte	the Cityle nen	d south of this site, resulting		
3	Sediment - This site has disrupted the drainage pattern into the City's pond south of this site, resulting							
in significant erosion and sediment damage in the city's Municipal Separate Storm Se Phase 1 construction did not provide a non-erosive outfall in violation of CGP 2.2.11.								
						•		
	<b>Mediation:</b> Restore erosion and remove sediment deposits in the city's MS4 in accordance with restoration Plan approved to be in the Work Order (WO) Plans for Phase 2. Also construct infrast							
	to prevent further erosion and sediment per revised WO plans approved by the city.							
2.1	Discharge off site?	(Y/N)	yes					
4	Self Inspec	tion Reports	OK	Latest rep	oort Date:	8/27/2025		

Notes:	SWPPP is in main office.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: James Hughes (505) 924-3420

jhughes@cabq.gov

9/4/2025

James D. Hughes