



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	K08E003	Project Name:	West Mesa RV Park		
NPDES Id. No.	NMR1003H4	Location:	Volcano Rd and 102nd St. NW		
8/13/2021	Owner	Contractor			
Operator	S.M. Quraishi	Shakeel Rizvi			
Contact name & title	S.M. Quraishi	Shakeel Rizvi			
e-mail	smquraishi@yahoo.com	shaky1424@yahoo.com			
Contact Phone #	505-379-6643	505-315-6563			
COA Inspector	Doug Hughes	Start/End Time:	4pm		
Construction Phase:	earthwork				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?		clear	Temperature: ~		93
Estimated date of last storm 0.25" or greater		7/31/2021			
Item Number	Deficiency/ Corrective Action				
1	all previous areas of concern mitigated				
2					
3					
4					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Received	Latest report Date:	8/13/2021	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Doug hughes (505-803-6215)
jhughes@cabq.gov

8/17/21

James D. Hughes