



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	K08E004	Project Name:	Mister Carwash		
NPDES Id. No.	NMR1002LG	Location:	201 98th St.		
7/1/2021	Owner			Contractor	
Operator	Dave Hail			HBA CORP Construction	
Contact name & title	Dave Hail			Martin Armijo	
e-mail	Dhail@mistercarwash.com			marmijo@benningconstruction.com	
Contact Phone #	520-907-8130			505-916-6463	
COA Inspector	Thomas Evans	Start/End Time:		11:15 AM-11:20 AM	
Construction Phase:		Stabilization			
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?		clear		Temperature: ~ 79	
Estimated date of last storm 0.25" or greater		6/28/2021			
Item Number	Deficiency/ Corrective Action				
1	No posting of permit coverage. Re-post permit coverage in a location visible to the public.				
2	Install perimeter control BMP. A sediment control BMP needs to be installed and maintained until final stabilization is accepted by the City.				
3	Provide self-inspection reports. Inspection reports must continue every 14 days until final stabilization is accepted by the City.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	8/13/2020	

Notes:	Spoke with Martin and discussed the final stabilization criteria and actions to be taken.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans 07/02/2021