Enterprise Builders: Utility Trailer of Colorado





Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine

Date: 01-22-2019

Time: 11:29 AM

Permit Tracking #: NMR1001BL

Inspector Name: Carlos Flores

Qualifications: CISEC

Current Weather Conditions: Light Snow Showers (Isolated) Date and Amount of Last Recordable Storm Event: 1"

Construction Time Line:

Sonstaction Time Line.								
Action	Start Date	Date Complete						
Initial BMP Installation	07-31-2018							
Clearing and Grubbing	08-06-2018							
Utility Installation								
Construction of Structure	3 200 - X							
Final Stabilization		01-22-2019						

Site Walk:

Site Walk: Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			×	Paving being installed
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			X	
Silt Fence		\boxtimes		
Wattles/Filter Sock	X			
Inlet Protection	\boxtimes			
Cut Back Curbs			X	
Waste Management		X		
Vehicle Tracking Control	X			VTC has been removed for paving. Sweeping will be done regularly
Material Storage	×			
Dust Control	X			
Street Sweeping	X			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.			×	
Discharge Points	X			
Sanitary Stations	X			
Stockpiles			X	
Other			X	

Enterprise Builders: Utility Trailer of Colorado

NMR1001BL

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	×			
Was the SWPPP updated at the time of the inspection?	×			
Are all certification pages signed?	X			
Are inspector qualifications in the SWPPP?	X			
Is there a copy of the NOI and Acknowledgement letter?	×			
Is there a delegation letter in the SWPPP?	X			
Was the last inspection/CAL certified?	X			
personnel properly gathered and evaluated the information subn	nitted. Bas le best of r	ed on my i ny knowle	inquiry of the	direction or supervision in accordance with a system designed to assure that qualified the person or persons who manage the system, or those persons directly responsible lief, true, accurate, and complete. I am aware that there are significant penalties for

submitting false information, including the possibility of fine and imprisonment for knowing violations.

Owner			
	Name	Signature	Date
Operator	r: Andrew chavez	Cre8	01-22-2019
	Name	Signature	Date

Additional Comments:

Enterprise Builders: Utility Trailer of Colorado

NMR1001BL



Action Log:

Location	Action Type	Action Required	Date Noted	Date Gompleted	Initials
Southside of site	Maintenance	Re trench silt fence or install additional controls to prevent sediment from leaving the site	01-08-2019		
blow trash		Clean up trash along south side of site	01-08-2019	01-22-2019	357 11

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of line and imprisonment for knowing violations."

Inspector:			
	Name	Signature	Date



City of Albuquerque Stormwater Construction Site Inspection Report

			neral Information				
Project Name and Location		Utility	Trailer 50 Hona RE	vies			
		8201 Da	Hona RE	NW			
Site Conta	act Name & Agency	Andrew Chi Enterprise	ave 7	ESC File No. NPDES ID No.	KOG EU268		
Date of In	spection	2.6-19		Start/End Time 9:2	2019:25		
COA Inspector Name Curtis Cherne, Stormwater Quality							
Describe l Phase	Present of Construction	Stabilite					
Type of In	nspection:		m event (> 0.25 inch) •	311 / Complaint Res	ponse · Follow-Up		
		Wes	ather Information				
	at time of this inspection	on? tain • Sleet • Fo	g · Snowing ·	Tem Windy	perature: ~ \frac{75}{F^\circ} F^\circ		
Has there Amount:	been a storm event si	nce the site was Permi		,			
		-	Inspection				
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required		Location and Notes			
1.5	Post a Notice		1				
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft						
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control along any perimeter						
2.2.4	Minimize sediment track	-					

:

2.2.5	Manage stockpiles						
2.2.6	Minimize Dust						
2.2.10	Protect Storm Drain Inlets			31-11			
2.2.10	Protect Storm Drain Inlets						
2.2.11	Minimize erosion of conveyance channels						*
2.2.12	Sediment Basins						**
2.2.14	Stabilize exposed portions of the site.						
2.2.14	Stabilize exposed portions of the site.						
2.2.14	Stabilize exposed portions of the site.						
2.2.14	Stabilize exposed portions of the site.						
2.3.1	Equipment and Vehicle Fueling						
2.3.2	Equipment and Vehicle Washing			Stabilize L			
2.3.3	Building Material Storage						
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage						***
2.3.3	Construction and Domestic Wastes			1			
2.3.3	Construction and Domestic Wastes						
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.						
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.				. =0.	-	
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.						
2.4	Dewatering						
2.1	Discharge off site?	· Yes · No					
4	Self-Inspection Reports		Latest	Report Date:			
¹ Constru	ity Inspector Use) Items in action General Permit (C ance or corrective action	CGP)					
Notes:		· · · · · · · · · · · · · · · · · · ·					
	<u></u>						
-							
	250)				<u>.</u>		
	y of Albuquerque Storm	_		/	n + r /	1	2-6-19
City	y of Albuquerque Storm	water Inspecto	r Signat	ure and Date:	Signa	ture	Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
Project Na and Lo	,	041H	of Destars	les Rd 1211	
Site Contact Name & Agency			of Daytona chavez is Builler	ESC File No. NPDES ID No.	K09E026B
Date of In	spection	1-17-		Start/End /! 6	0/2:15
COA Insp	ector Name			Stormwater Quality	
Describe I Phase Type of Ir	of Construction	bldg con	plate, propins	for paving)
egu	lar • During storm	event • Post-	storm event (> 0.25 inch)	311 / Complaint Res	ponse · Follow-Up
			Weather Information		
CI		in • Sleet •		Tem Windy	perature: ~ F°
Has there Amount:	been a storm event sha • < 1/4" • 1/4" • 0 3/4"		ermitted? Yas · No	77	
			Inspection		
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required		Location and Notes	
1.5	Post a Notice				
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft				
2.2.3	Sediment control along any perimeter		Sodimut in 50	heet and ba	h guffers
2.2.3	Sediment control along any perimeter		no selimot	BMP for po	vkin ann
2.2.3	Sediment control along any perimeter		but rame in	1 4 A	parking area
2.2.3	Sediment control along any perimeter				•
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.4	Minimize sediment track- out		entiry roadwo	y from the	soul ater
			disposing of wa	sk- no utc	·



*			
2.2.5	Manage stockpiles		
2.2.6	Minimize Dust		
2.2.10	Protect Storm Drain Inlets	~	Street in let protection region maintance
2.2.10	Protect Storm Drain Inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		<u> </u>
2.2.14	Stabilize exposed portions of the site.		
2.3.1	Equipment and Vehicle Fueling		
2.3.2	Equipment and Vehicle Washing		
2.3.3	Building Material Storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and Domestic Wastes	V	wask not in confairer X2 numerous
2.3.3	Construction and Domestic Wastes		Concrete wash-out
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	/	concrete wash-out
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site?	· Yes · (No)	
4	Self-Inspection Reports	request	Latest Report Date: /- 8-1 9
Notes: (C	ity Inspector Use) Items i	n convoliance ca	n he left blank

Notes: (City Inspector Use) Hems in compliance car

1 Construction General Permit (CGP)

Construction General Lethit (CGL)	
Maintenance or corrective actions are to be completed within '	7 days

Notes: Darin			
Sweeping stre	+ before P	left	
F ₂₂			

City of Albuquerque Stormwater Inspector Signature and Date: Line Company 1-17-19

Signature Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov



Enterprise Builders: Utility Trailer of Colorado



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine

Date: 01-08-2019

Time: 10:10 AM

Permit Tracking #: NMR1001BL

Inspector Name: Carlos Flores

Qualifications: CISEC

Current Weather Conditions: clear

Date and Amount of Last Recordable Storm Event: 1"

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	07-31-2018	
Clearing and Grubbing	08-06-2018	
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Site Walk: Question	Yes	No	N/A	Comment
Is there a proper posting sign?	X			
Are areas that have been disturbed, but not under construction been properly stabilized?			×	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			×	
Silt Fence		X		
Wattles/Filter Sock	X			
Inlet Protection	X			
Cut Back Curbs			×	
Waste Management		X		
Vehicle Tracking Control	X			VTC has been removed for paving. Sweeping will be done regularly
Material Storage	×			
Dust Control	X			
Street Sweeping	X			
Construction Washouts i.e. Concrete, Paint, Stucco Etc.	×			
Discharge Points	X			
Sanitary Stations	×			
Stockpiles	×			Small stockpiles are being used regularly
Other			X	

Enterprise Builders: Utility Trailer of Colorado

NMR1001BL

Date

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?				
Was the SWPPP updated at the time of the inspection?	×			
Are all certification pages signed?				
Are inspector qualifications in the SWPPP?	×			
Is there a copy of the NOI and Acknowledgement letter?	×			
Is there a delegation letter in the SWPPP?	X			
Was the last inspection/CAL certified?	X			
personnel properly gathered and evaluated the information sub-	mitted. Bas he best of 1	ed on my my knowle	inquiry of t dge and be	direction or supervision in accordance with a system designed to assure that qualifie he person or persons who manage the system, or those persons directly responsible slief, true, accurate, and complete. I am aware that there are significant penalties for atlons."
Name Signature				Date
Constant Andrew shows	2	C	S	01.00.2010

Name

Additional Comments:

Signature

Enterprise Builders: Utility Trailer of Colorado






Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Southside of site	Maintenance	Re trench silt fence or install additional controls to prevent sediment from leaving the site	01-08-2019		
blow trash		Clean up trash along south side of site	01-08-2019		


"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."


	ne		

Vame	Signature	Date
400110		




8-7-18






8-7-18




8-7-18





8-21-18






1-8-19





1-8-19



Cherne, Curtis

From:

Cherne, Curtis

Sent: To: Thursday, January 17, 2019 3:52 PM Andrew Chavez (AChavez@ebnm.com)

Subject:

Utility Trailer Sales Construction Site Inspection

Attachments:

dirt_bruckners.jpg; street.jpg; north_gutter.jpg; south_edge.jpg; inlet_closeup.jpg; no_track-

out_pad.jpg; wash-out.jpg; trash2.jpg; trash.jpg; indequate_trash_container.jpg;

Utility_Trailer_Inspection_Report_1-17-19.pdf

Andrew,

Good afternoon.

The following issues were observed at today's inspection.

- 1. Sediment in Daytona Rd and gutters down to Bruckner. Please remove.
- 2. The inlet protection in Daytona requires maintenance, but since the paving will occur at the end of this week and next week, once the street is paved, remove the inlet protection and dirt from the inlet area.
- 3. A loader was entering the roadway from a dirt area without Vehicle Tracking Control.
- 4. There was concrete wash-out south of the fence. Please dispose of properly and have all subs use the wash-out pit you have.
- 5. There was trash and waste not in an acceptable trash container. Not showing all pics of trash/waste to reduce e-mail size. There was also trash outside the fence in the SE corner.
- 6. Some of the wastes/trash were put in an open wood box. This is not an acceptable waste container. They are to be leak-proof and have the ability to be covered. Most folks are using a tarp.

I thanked Darren for taking the time for me to go over this stuff with him.

Please send your latest SWPPP self-inspection report. Thanks,



CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

Cherne, Curtis

From: Sent: To: Cc: Subject:	Cherne, Curtis Friday, October 26, 2018 4:10 PM 'Andrew Chavez' Luke Harwood RE: 8201 Daytona St Nw
Andrew, Thanks for sending the pics Street almost looks clean e	nough to eat off of. Thanks Gutter may have a touch too much sediment in it.
A couple of tips:	
the bags. If on grade (not	I for inlet protection if the inlet is in a low-spot as the drainage will have to go up and over in low-spot) you may want to consider a different style (coca mat, mulch sock) that lets water oks like it will prevent sediment and wastes from entering the inlet.
	the sandbag in front of the rock bag in Daytona. The "L" area collects sediment. The rock ugh, where the sandbag won't. This would work better without the sandbag.
Have a good weekend.	
CURTIS CHERNE, PE, QCIS principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning	
Original Message From: Andrew Chavez mai Sent: Friday, October 26, 26 To: Cherne, Curtis Cc: Luke Harwood Subject: 8201 Daytona St N	018 9:27 AM
Curtis, here is a few photos	of the Street up keeping of Daytona St.
Call me if you have any que	estions.
Thanks.	
	-
	lyzed by Deep Discovery Email Inspector.



Cherne, Curtis

From:

Andrew Chavez < AChavez@ebnm.com>

Sent:

Sunday, October 07, 2018 7:16 AM

To:

Cherne, Curtis

Cc:

Luke Harwood; David Lundsten

Subject:

8201 Daytona St

Attachments:

IMG_3187.JPG; ATT00001.c; IMG_3186.JPG; ATT00002.c; IMG_3184.JPG; ATT00003.c;

IMG_3183.JPG; ATT00004.c; IMG_3188.JPG; ATT00005.c

Curtis, here is photos you requested, last week for dust control and sediment stabilization on 8201 Daytona St.

Thanks,

This message has been analyzed by Deep Discovery Email Inspector.

Cherne, Curtis

From:

Andrew Chavez < AChavez@ebnm.com> Thursday, October 04, 2018 6:56 PM

Sent: To:

Cherne, Curtis

Subject:

Re: Utility trailer of Colorado inspection report and mitigation of "Action Required" items

Sure thing Curtis.

Thanks.

Sent from my iPhone

On Oct 4, 2018, at 4:04 PM, Cherne, Curtis < CCherne@cabq.gov> wrote:

Andrew,

I received the inspection report dated 10-2-18 for your site. Thanks. I noticed the "Action Required" items and viewed the pics in the report.

Please send pictures by 10-9-18, that these items have been mitigated.

Thanks,

<image002.jpg>

CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality

- o 505.924.3420
- e ccherne@cabq.gov

cabq.gov/planning

This message has been analyzed by Deep Discovery Email Inspector.

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Thursday, October 04, 2018 4:04 PM

To:

Andrew Chavez (AChavez@ebnm.com)

Subject:

Utility trailer of Colorado inspection report and mitigation of "Action Required" items

Andrew,

I received the inspection report dated 10-2-18 for your site. Thanks. I noticed the "Action Required" items and viewed the pics in the report.

Please send pictures by 10-9-18, that these items have been mitigated.

Thanks,



curtis cherne, Pe, Qcis principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

Enterprise Builders: Utility Trailer of Colorado



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine

Date: 10-02-2018

Time: 11:03 AM

Permit Tracking #: NMR1001BL

Inspector Name: Carlos Flores

Qualifications:

Current Weather Conditions: Thunderstorms (Scattered) Date and Amount of Last Recordable Storm Event: N/A

Construction Time Line:

Action	Start Date	Date Gomplete
Initial BMP Installation	07-31-2018	
Clearing and Grubbing	08-06-2018	
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	X			
Are areas that have been disturbed, but not under construction been properly stabilized?			×	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			×	
Silt Fence		×		
Wattles/Filter Sock		×		
Inlet Protection		X		
Cut Back Curbs			×	3.48
Waste Management			\boxtimes	
Vehicle Tracking Control		X		910
Material Storage			\square	
Dust Control	×			
Street Sweeping		×		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.		×		
Discharge Points	X			
Sanitary Stations	X			
Stockpiles			X	
Other			×	



Enterprise Builders: Utility Trailer of Colorado

NMR1001BL

Date

SWPPP Information:

Question	1	Yes	No	N/A	Comment
Is the SWPPP kept on site?		X			
Was the SWPPP updated at the inspection?	e time of the	×			
Are all certification pages signe	ed?				
Are inspector qualifications in t	he SWPPP?				
is there a copy of the NOI and letter?	Acknowledgement	×			
Is there a delegation letter in th	Is there a delegation letter in the SWPPP?				
Was the last inspection/CAL certified?					
personnel properly gathered and eval	uated the information sub smation submitted is, to t	mitted. Bas he best of r	ed on my ny knowle	inquiry of t dge and be	direction or supervision in accordance with a system designed to assure that qualifier the person or persons who manage the system, or those persons directly responsible life, true, accurate, and complete. I am aware that there are significant penalties for ations."
Name	Signature				Date
Operator: Andrew chavez	α	ul	.Ce	8	10-02-2018

Name
Additional Comments:

Signature



Enterprise Builders: Utility Trailer of Colorado



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
East Perimeter: Silt Fence	Maintenance	Need to repair the damaged silt fence	09-04-2018		
northeast perimeter - filter sock	Maintenance	Remove, clean and replace filter sock due to dirt pushed over top	09-18-2018		
north side of construction entrance	Maintenance	Install controls to minimize sediment leaving the site	10-02-2018		9 3
site entrance - inlet protection	Maintenance	Clean inlet protection for sediment and trash	10-02-2018		
inlet protection	Corrective Action	Install inlet protection	10-02-2018		
concrete was hout area	Corrective Action	Clean up concrete spoils - concrete washout needs to be relined to keep concrete washout contained	10-02-2018		
Owner Cert Page	Maintenance	Need to sign	09-04-2018		

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."


inspector			
	Name	Signature	Date

or .			

Site Walk Deficiency Photos - northeast perimeter - filter sock



Site Walk Deficiency Photos - north side of construction entrance




Site Walk Deficiency Photos - site entrance - inlet protection





Site Walk Deficiency Photos - concrete washout area







8-7-18



		iii.		
	14.			



8-7-18



		8	



8-21-18

Cherne, Curtis

From: Cherne, Curtis

Sent: Tuesday, October 02, 2018 7:42 AM

To: 'Green Globe'; Andrew Chavez (AChavez@ebnm.com)

Subject: RE: Green Globe Enterprise Builders: Utility Trailer of Colorado - Storm Water Compliance

Inspection Form-newer report?

Tim/Andrew,

Don't worry about the rain event report.

If regular reports are being done, that is what I am looking for.

Please send latest report, which should have been done within the past two weeks, and that will suffice to clear the current violation.



CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

From: Green Globe [mailto:tim@greenglobenm.com]

Sent: Monday, September 24, 2018 4:12 PM

To: Cherne, Curtis

Subject: Re: Green Globe Enterprise Builders: Utility Trailer of Colorado - Storm Water Compliance Inspection Form-

newer report?

Curtis.

We will be doing one tomorrow. Let me check on the rain event.

Sent from my iPhone

On Sep 24, 2018, at 4:02 PM, Cherne, Curtis < CCherne@cabq.gov > wrote:

Tim,

Thanks for the report, but it is from 9-4-18. Today is the 24th, seems you should have one from the 18th or from the 20th/21st as it appears there was a qualifying event on 9-19-18. See attached image from CoCoRaHS. It has the 20th as the date, but that is the report date which is at 7AM. It is for the precip in the 24 hours preceding it.

Please provide a more recent report.

<image003.jpg>

CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality

o 505.924.3420

e ccherne@cabq.gov

cabq.gov/planning

From: CloudCompli [mailto:greenglobe@compli.cloud]

Sent: Monday, September 24, 2018 12:15 PM

To: Cherne, Curtis

Subject: Green Globe Enterprise Builders: Utility Trailer of Colorado - Storm Water Compliance

Inspection Form

Tim Slatunas (tim@greenglobenm.com) has sent you the following report via CloudCompli:

Storm Water Compliance Inspection Form at Enterprise Builders: Utility Trailer of Colorado on 2018-09-04

The report may be accessed here:

https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=https%3a%2f%2fgreenglobe.compli.cloud %2fpublic%2flocations%2f14064%2freports%2f47773%2femail%2f0d0d3f7b1cce0fda154152b 40ee2791c&umid=4D985CF7-76A1-F605-847C-

<u>E6563CC8308C&auth=f0ebcd052f61e7a39dc93191e8a01d02608499af-bd4e50a2d6e933bef38355d3d4f3f566620f002c</u>

If clicking the link doesn't redirect you to a download page, try copy and pasting the URL into your browser instead. Otherwise, contact CloudCompli Support.

Note that CloudCompli does not support Internet Explorer. For better security, speed, compatibility, and an overall better experience, we recommend you use up to date modern browsers like <u>Chrome</u>, <u>Firefox</u>, <u>Opera</u>, <u>Safari</u>, or <u>Microsoft Edge</u>.

This message has been analyzed by Deep Discovery Email Inspector.

<storm 9-19-18.JPG>

This message has been analyzed by Deep Discovery Email Inspector.

Enterprise Builders: Utility Trailer of Colorado



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 09-04-2018 Time: 9:45 AM

Permit Tracking #: NMR1001BL Inspector Name: Tim Slatunas Qualifications: CESSWI CISEC

Current Weather Conditions: Clear Date and Amount of Last Recordable Storm Event: N/A

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation	07-31-2018	
Clearing and Grubbing	08-06-2018	
Utility Installation		26.00
Construction of Structure		
Final Stabilization		N

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?		X		Sign will be installed this week
Are areas that have been disturbed, but not under construction been properly stabilized?			X	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			X	
Silt Fence		×		
Wattles/Filter Sock	X			
Inlet Protection	X			
Cut Back Curbs			×	
Waste Management			×	
Vehicle Tracking Control				
Material Storage			X	
Dust Control	X			
Street Sweeping		X		
Construction Washouts i.e. Concrete, Paint, Stucco Etc.			×	
Discharge Points	×			L.W.
Sanitary Stations	×			
Stockpiles			X	
Other			×	

Enterprise Builders: Utility Trailer of Colorado

NMR1001BL

SWPPP Information:

Question	Yes	No	N/A	Comment
Is the SWPPP kept on site?	X			40.5 (3)4
Was the SWPPP updated at the time of the inspection?	X			
Are all certification pages signed?		X		
Are inspector qualifications in the SWPPP?	X			
Is there a copy of the NOI and Acknowledgement letter?	×			
Is there a delegation letter in the SWPPP?	X			
Was the last inspection/CAL certified?	×			

Owner:		
Name	Signature	Date
	andles	
Operator: Andrew Chavez		09-04-2018
Name	Signature	Date

Additional Comments:

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Enterprise Builders: Utility Trailer of Colorado





Action Lon:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
East Perimeter: Silt Fence	Maintenance	Need to repair the damaged silt fence	09-04-2018		1 (4) (4)
Site Entrance	Maintenance	Need to establish some kind of tracking control	08-21-2018	09-04-2018	
Daytona: Sweeping	Maintenance	Need to sweep for sediment in the street	08-21-2018	09-04-2018	
Owner Cert Page	Maintenance	Need to sign	09-04-2018		


[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector	9			
	Name	Signature	Date	


Site Walk Deficiency Photos - East Perimeter: Silt Fence




Site Walk Deficiency Photos - Owner Cert Page




8-7-18





8-7-18





8-21-18




City of Albuquerque

Planning Department

Stormwater Control Permit for Erosion and Sediment Control

Project Title <u>Utility Trailer Sales</u>
Project Location (Major Cross Streets/Arroyo or address) 8201 Daytona Rd NW Albuquerque NM 87121
Property Owner: (Note: If applying for a Building Permit, the "Company" or "Owner" name on this form must match the "Owner" name on the Building Permit.)
Company Name or Owner Name: <u>Utility Trailers Sales, Inc.</u>
Responsible Person: (Note: Name below may be the same as Owner Name above if there is no Company Name Name: Jeff Martin
Phone Number: <u>303-886-5427</u>
E-mail: jbmartin@utilitytrailer.net
Site Contact: (if different than Property Owner info above.)
Name:
Phone:
e-mail:
For City personnel use only:
City Personnel Signature: Curtu a. Cherne Date 7-19-18
(Rev June 2017)



From:

Cherne, Curtis

Sent:

Monday, September 24, 2018 8:44 AM

To:

jbmartin@utilitytrailer.net

Cc:

Andrew Chavez (AChavez@ebnm.com)

Subject:

Utilty Trailer Sales Violation Letter

Attachments:

K09E026B_Violation_Letter.pdf

Jeff,

See attached letter.



CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

CITY OF ALBUQUERQUE



September 24, 2018

Jeff Martin, Utility Trailer Sales, Inc., jbmartin@utilitytrailer.net Copy: Andrew Chavez, Enterprise Builders, achavez@ebnm.com

Site: Utility Trailer Sales-8201 Daytona Rd NW

Re: Drainage Ordinance (14-5-2-1) Violations for Erosion and Sediment Control

Dear Mr. Martin,

1. Self-inspection reports have not been submitted.

Self-inspections and accompanying reports are required once every 14 days and within 24 hours after a precipitation event of 0.25 inch or greater.

Required mitigation:

PO Box 1293

1. Perform self-inspections and document conditions on an inspection report(s) and provide the report(s) to the City.

Albuquerque

Self-inspection reports can be hand-delivered, e-mailed or kept on-site. If kept on-site, the location is to be communicated to the City and the location must be accessible to the City during regular work hours.

NM 87103

If the violations are not mitigated within 30 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you have any questions, you can contact me at 924-3420, ccherne@cabq.gov.

www.cabq.gov

Sincerely, Curtin a Chem

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

From:

Cherne, Curtis

Sent:

Thursday, August 30, 2018 7:55 AM

To:

jbmartin@utilitytrailer.net

Subject:

Utility Trailer Sales Construction Site Inspection

Attachments:

storm_drain_protection.jpg; inlet_protection_maintenance.jpg; sediment_gutter.jpg;

bruckner_sediment_street.jpg

Jeff,

Good morning.

I was out at your site yesterday for a follow-up inspection.

Previous issues were addressed. Thanks.

However, the following issues were observed:

- 1. The existing storm drain did not have inlet protection. Please provide.
- 2. The inlet protection in Daytona Rd requires maintenance.
- 3. Too much sediment in north gutter pan of Daytona Rd. Please remove.

Please provide the last self-inspection report. The report can be hand-delivered, e-mailed, electronically accessed or kept on-site. If kept on-site please let me know where reports are kept.

For informational purposes. I stopped in to Bruckner Truck Sales and asked them to remove the sediment in the street near their eastern property line.

Standard mitigation time is seven days. If you prefer, photos of the mitigation can be e-mailed to me in lieu of another physical site inspection.



CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning



City of Albuquerque Stormwater Construction Site Inspection Report

1/10/07/07/07/07						
	General Information					
Project Name	Utility Trailer Sales					
and Location	8201 Doytone BY NE					
Site Contact Name & Agency	Jeff Martin ESC File No. 1604B02617					
Date of Inspection	9-7-18 Start/End 9:21/					
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Describe Present Phase of Construction	aparting, reber for fin					
Type of Inspection:						
- Regular • During stor	m event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up					
	Weather Information					
Weathor at time of this inspect	on? Temperature: ~/OF° Rain · Sleet · Fog · Snowing · Windy					
Has there been a storm events	nce the site was Permitted? 'Ye' No					
Amount: • < 1/4" • 1/2" to 3	4" · > 34" · Snow"					
	Erosion & Sediment Control Inspection					
Entrance / Track-Out Track-Out Track of South South Surver Araby Cross at Track of the track of the broken Warm Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc. Sediment (A North guffer on Dayforce Drocken entrance Limber of arkase in dark war cost of 51 H. Interior porduce						
w/ so where	tracking control					
Inspection Reports Erosion Controls Housekeeping/Pollutant Controls O O O O O O O O O O O O O						
Debris/Pollutants/Sediment in MS4 NO tes						
Is site being maintained in complian	ce with the Drainage Ordinance? Yes (No) Lute C che 97-18 Signature Date					

From: Sent: Andrew Chavez < AChavez@ebnm.com> Monday, September 17, 2018 11:12 AM

To: Subject: Cherne, Curtis 8201 Daytona rd me

Attachments:

IMG_2909.JPG; ATT00001.c; IMG_2910.JPG; ATT00002.c; IMG_2913.JPG; ATT00003.c;

IMG_2914.JPG; ATT00004.c

Curtis, here is photos of our site, per you request here for 8201 Daytona st.

Please fill free to contact me if you are any questions in regards of the over all up keeping.

This message has been analyzed by Deep Discovery Email Inspector.



From:

Cherne, Curtisy

Sent:

Friday, September 07, 2018 3:25 PM

To:

jbmartin@utilitytrailer.net

Subject:

Utility Trailer Sales Construction Site Inspection

Attachments:

track-out.jpg; worker_parking.jpg; parking_tire_tracks.jpg; sediment_gutter.jpg;

sediment_gutter2.jpg; sediment_gutter3.jpg

Jeff.

Good afternoon.

I was out at your site today as it was 8 days since my previous inspection and I had to follow-up on the inlet protection. I noticed the inlet protection. Thanks.

However the following issues were observed:

- 1. Medium amount of track-out. The current track-out pad is not as effective as it should be. I saw one truck roll over it at 15 to 20 mph. It is too smooth and not creating enough bounce. Therefore, the track-out. Please remedy and remove sediment from Daytona Road including the gutters.
- 2. Workers are parking in the dirt to the east of the project on the south side of the road and there is no vehicle tracking control. Please implement. Instead of a track-out pad, possibly a gravel "area" my function adequately and it may be difficult to have workers leave at one location. Another option is to have them park on-site.
- 3. Please provide the last self-inspection report.



CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

	47		
		*5	
到			
	5		

From:

Cherne, Curtis

Sent:

Tuesday, September 18, 2018 12:45 PM

To:

'Andrew Chavez'

Subject:

RE: 8201 Daytona rd NW-response

Andrew,

Thanks for sending the pics.

A couple things:

- 1. Please send the latest self-inspection report. The owner has not responded to my last two requests for reports. His time was running out. I'd prefer to not send a letter, especially if you are doing them. Please send self-inspection report by this Friday, 9-21-18.
- 2. IMG_2909.jpg shows a couple of cars in the dirt on the south side of the road. If workers are parking over there, you need track-out control. I don't see it in the pic. Please explain.

Thanks,

curtis cherne, Pe, Qcis principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

----Original Message----

From: Andrew Chavez [mailto:AChavez@ebnm.com]
Sent: Monday, September 17, 2018 11:12 AM


To: Cherne, Curtis

Subject: 8201 Daytona rd me

Curtis, here is photos of our site, per you request here for 8201 Daytona st.

Please fill free to contact me if you are any questions in regards of the over all up keeping.

This message has been analyzed by Deep Discovery Email Inspector.



From:

Andrew Chavez < A Chavez @ ebnm.com>

Sent:

Friday, September 21, 2018 8:54 AM

To:

Cherne, Curtis

Subject:

RE: 8201 Daytona rd NW-response

Hello Curtis, the have been directed to park in the private property side.

Thanks,

----Original Message----

From: Cherne, Curtis [mailto:CCherne@cabq.gov] Sent: Tuesday, September 18, 2018 12:45 PM

To: Andrew Chavez

Subject: RE: 8201 Daytona rd NW-response

Andrew,

Thanks for sending the pics.

A couple things:

1. Please send the latest self-inspection report. The owner has not responded to my last two requests for reports. His time was running out. I'd prefer to not send a letter, especially if you are doing them. Please send self-inspection report by this Friday, 9-21-18.

Styll new reputs

2. IMG_2909.jpg shows a couple of cars in the dirt on the south side of the road. If workers are parking over there, you need track-out control. I don't see it in the pic. Please explain.

Thanks,

curtis cherne, Pe, Qcis principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

----Original Message-----

From: Andrew Chavez [mailto:AChavez@ebnm.com]
Sent: Monday, September 17, 2018 11:12 AM

Sent. Monday, September 17, 2010 11

To: Cherne, Curtis

Subject: 8201 Daytona rd me

Curtis, here is photos of our site, per you request here for 8201 Daytona st.

Please fill free to contact me if you are any questions in regards of the over all up keeping.

This message has been analyzed by Deep Discovery Email Inspector.

This message has been analyzed by Deep Discovery Email Inspector.



City of Albuquerque Stormwater Construction Site Inspection Report

	General Informa	tion				
Project Name and Location	Utility Trailer 8201 Daytona	saus				
and Docation	8201 Day tona	RL NW				
Site Contact Name & Agency	Jeff Martin	ESC File No	. Kog Eons			
	Whiley Trails Soles					
Date of Inspection	8-29-18	Start/End Time	11.20/11:45			
Inspector Name, COA Dept.	Curtis C	herne, Stormwater Qu	ality			
Describe Present Phase of Construction	grading/exporting					
Type of Inspection:	, , ,					
Regular	m event • Post-storm event (> 0.5 in	nch) - 311 / Complain	t Response · Follow-Up			
	Weather Informa	ntion				
Weather at time of this inspecti	on? Rain • Sleet • Fog • Snowin	g • Windy	Temperature: ~F°			
Has there been a storm event si	nce the site was Permitted? · Yes	• No				
Amount: • < 1/4" • 1/4" to 3	4" · > 3/4" · Sno	w"				
Erosion & Sediment Control Inspection						
Entrance / Track-Out Pal	Ol - no prock-out					
Sediment Controls / Silt Fence, 11th projection on Day for reless months. Inlet Protection, Wattles, etc. Sedende in gueffica						
	ı r					
Inspection Reports required						
Erosion Controls NO Housekeeping/Pollutant Controls NO						
Debris/Pollutants/Sediment in Notes 5- production and Sediment in 2. Remain Sediment Sediment in 2. Remain Sediment Sedime	MS4 M + Bruckner Twi on Mighba Conghroch which from Days	at site of som	Fist Slux culus			
Is site being maintained in complian	ce with the Drainage Ordinance?* Yes	No) Late 6 a	Date			

69				
	9			
v.				



City of Albuquerque Stormwater Construction Site Inspection Report

and the second s							
	General Infor						
Project Name	Utility traite	. Sale	۷				
and Location 8201 Daytona Rd Nh							
Site Contact Name & Agency	Jeff Markin Uhlity Trails Sale		ESC File No.	KOGEOZUS			
Date of Inspection	0-7-18		Start/End /0'	30/10:55			
Inspector Name, COA Dept.	Curtis	s Cherne, St	ormwater Quality	/			
Describe Present Phase of Construction	Stortel expirt						
Type of Inspection: Regular • During stor	,	5 inch) • 3	11 / Complaint Resp	onse · Follow-Up			
<u> </u>	Weather Infor	mation					
Weather at time of this inspect	ion? Rain • Sleet • Fog • Snow	ving -	Tem Windy	perature: ~ 85 F°			
Has there been a storm event s		es · No					
Amount: • < 1/4" • 1/4" to 3	¼" · > ¾" · S	now''					
	Erosion & Sediment Co	-					
Entrance / Track-Out	trackout pad mi	1 Nach	50017 -11	freck -out			
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.		to which	Dayfur - h	an pollfu			
500d 5,11 fum,	istal east side						
	WHI						
Housekeeping/Pollutant Controls							
Debris/Pollutants/Sediment in Notes 10 psychology	MS4 30" SD but pure , Scoling Builder	Ed 1	i will war	h, may			
Is site being maintained in complian	ce with the Drainage Ordinance ?* Yes	_ / _	Cuto 6 C	Pare 10			

ų.				
	75			
		×		
			*	

From:

Cherne, Curtis

Sent:

Tuesday, August 07, 2018 4:24 PM

To:

jbmartin@utilitytrailer.net

Subject:

Utility Trailer Sales - 8201 daytona Rd 87121- Construction Site Inspection

Attachments:

inlet_protection.jpg; dirt_pile_asphalt.jpg; storm_drain.jpg; storm_drain_pond.jpg

Jeff,

Good afternoon.

I went by the project today for an inspection.

There were just getting started with the export.

Nice sediment BMP installations on east and north side.

Fabric was used on the grate of the drain inlet in Daytona Rd, however, on this style of inlet, drainage goes into the curb opening. The dirt pile is adjacent to the asphalt, so if it rains or if they overwater for dust control, the dirt will go into the inlet. Please provide inlet protection for the curb opening.

I am not sure how long you are leaving the cul-de-sac paving. The plan (Tierra West, 7-3-18) I have shows removal of the cul-de-sac with silt fence up to the edge of a track-out pad.

If it is to remain for a while, then a sediment BMP (silt fence/filter sock/straw wattle) should be placed to prevent dirt from getting onto the pavement. You also need Vehicle tracking control.

The plan I have also shows inlet protection for the storm drain on the south edge of the project. I don't think you need it today as there is a small ponding area north of the pipe to help keep sediment out of the pipe. Prior to grading in this area, please provide inlet protection for the storm drain.

Standard mitigation time is seven days. If you have any questions, or would like to discuss your phasing, please let me know.

ONE ALBUQUE RQUE

planning

CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420 e ccherne@cabq.gov cabq.gov/planning

Book pass on inch Arack - out hos gogns Full bis on wingers Full when who t

4				
		**		
	*			

K09 E026 B G, E, A




Rev April 2016

Stormwater Quality

ESC Plan Information Sheet

Project Name: Utility Trailer Sales	
Project Location: (address or major cross streets/arroyo)	
8201 Daytona Rd NW Alb, NM 87212	
Plan Preparer Information:	
Company:Tierra West LLC	
Contact: Vincent Carrica	
Address: 5571 Midway Pk PL, Alb, NM 87119	*****
Phone Number: (O) <u>505-858-3100</u> (Cell (optional))	
e-Mail: vcarrica@tierrawestllc.com	
Owner Information:	
Company: <u>Utility Trailer Sales</u>	
Contact: Jeff Martin	
Address: 920 Brighton, Henderson, CO 80640	
2516 University Blue NE 87/17	
Phone:303_886=5427	·
e-Mail: jbmartin@utilitytrailer.net	
I am submitting the ESC plan to obtain approval for:	DECEIVED
x ESC Permit-Grading	JUL 18 2018
x ESC Permit-Building Permit	LAND DEVELOPMENT SECTION
x Work Order Construction Plans	
Note: More than one item can be checked for a submittal	

If you have questions, please contact Curtis Cherne, Stormwater Quality 924-3420, ccherne@cabq.gov



CITY OF ALBUQUERQUE



July 19, 2018

Ron Bohannan, P.E. Tierra West, LLC 5571 Midway Park Pl NE Albuquerque, NM 87109

Re: Utility Trailer Sales

Erosion and Sediment Control Plan

Engineer's Stamp Date 7-3-18 Sht EC-1, 5-7-18 Sht EC-2(K09E026B)

Dear Mr. Bohannan,

Based upon the information provided in your submittal received 7-18-18 (Sht EC-1) and 5-8-18 (Sht EC-2), the above referenced plan is approved to be included in the SWPPP and to apply for an ESC Permit for grading and Building Permit. The plan is also approved to be included in the Work Order construction plans.

Include a copy of the approved plan in the Building Permit set.

PO Box 1293

Include a copy of the approved plan in the Work Order construction plans.

Albuquerque

If you have any questions, you can contact me at 924-3420.

NM 87103

www.cabq.gov

Cute a Cheine

Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

CITY OF ALBUQUERQ



May 21, 2018

Ron Bohannan, P.E. Tierra West, LLC 5571 Midway Park Pl NE Albuquerque, NM 87109

Re: **Utility Trailer Sales**

Erosion and Sediment Control Plan Engineer's Stamp Date 5-7-18 (K09E026B)

Dear Mr. Bohannan,

Based upon the information provided in your submittal received 5-8-18, the above referenced plan is not approved to be included in the SWPPP or to apply for an ESC Permit for grading and Building Permit until the following comments are addressed:

1. Provide existing and proposed grades and proposed inlets/pipes.

? 2. The plan appears to show silt fence across a paved road. Silt fence doesn't work on impervious surfaces unless a mulch sock or similar is placed at the bottom.

3. The information sheet did not include Work Order approval, therefore the disturbance would be limited to the southern property line and the silt fence on the southern side of the ROW is unnecessary.

a. If Work Order approval is requested, please let me know and in that case, propose inlet protection for the inlet(s) in the street east of the site and remove the sidewalk shown on the south side of the street as there is no sidewalk east of this site to tie-into. NO

4. What is proposed for the existing day-lighted storm drain on the site? The pipe opening should have a BMP prior to grading of the site.

5. Provide limits of the silt fence along the northern edge of the project.

6. I forget if the major source of run-on in the earthen arroyo has been cut-off by the I-40 channel, but you may still get some flow in the channel from an earthen basin(s) south of I-40 and from I-40 (inlet(s) in median?). How will this be addressed?

Additional comments may arise once grade/drainage improvements are provided.

If you have any questions, you can contact me at 924-3420.

Sincerely, Curtin G Cheme Curtis Cherne, P.E.

Principal Engineer, Stormwater Quality

Planning Dept.

PO Box 1293

Albuquerque

NM 87103

www.cabq.gov



KOGEO26B G, E, A



Stormwater Quality

ESC Plan Information Sheet

Project Name: _Utility Trailer Sales							
Project Location: (address or major cross streets/arroyo)	A >						
820 4550 Paradise Blvd. NW day from	RENN						
Plan Preparer Information:							
Company: _Tierra West, LLC							
Contact: Vince Carrica, PE	7.740						
Address: _5571 Midway Park Pl NE, Albuquerque, NM 87109							
Phone Number: (O) <u>505-858-3100</u> (Cell (optional)) _	····						
e-Mail: vcarrica@tierrawestLLC.com	,,,,						
Owner Information: Company:Utility Trailer Sales, Inc. Contact:Jeff Martin Address:9200 Brighton Road	The same than						
I am submitting the ESC plan to obtain approval for: X ESC Permit-Grading X ESC Permit-Building Permit Work Order Construction Plans	DECEIVED MAY 0 8 2018 LAND DEVELOPMENT SECTION						

Note: More than one item can be checked for a submittal If you have questions, please contact Curtis Cherne, Stormwater Quality 924-3420, ccherne@cabq.gov

Rev April 2016