

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Westpoint 40					
Location:		98th Street & Bluewater					
Site Contact Name &		Brian Patterso	n - Titan	ESC File No.		K09E041	
Agency		bpatterson@titar	ndevelopment.com	NPDES Id. No.	Oper:	NMR1002M/ Owr	ır: LEW
Inspection Date:		12/30/19 Start/End Time: 1120/1130hrs					
CoA Storm	water Inspector	r: Ti	mothy E. Sims				
	ction Phase:	earthwork					
Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow I							
Weath	er at time of i	nspection?	Clea	r	Tempe	erature: ~	32*
Estimated	date of last s	torm 0.25" or	greater			12/30/2019	
Item							
	Deficiency/ Corrective Action						
Number							
1	Install trackout pad at entrance/exitremove sediment t intersection of Adonai & Bluewater						
2	Owner's LEW not posted						
3	Please provide latest SWPPP self Inspection report.						
2.1		t. (c.)		1			
2.1	Discharge off site?	(Y/N)	No				CI
4	Self Inspect	ion Reports	requested	Latest rep	ort Date:	not on	TIIE
Notes: site at clear and grub stageperimeter silt fence installed, operator NOI posted and							
Fugitive dust permit at west end of Bluewater.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

12/30/19____